




report date: 2024-03-28

## General information

Make	VOLKSWAGEN
Model	TOUAREG SE TDI DPF
Colour	Silver
Year of manufacture	2007
Top speed	114 mph
0 - 60 mph	11.6 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	172 BHP
Max. torque	400 Nm at 2.250 rpm
Engine capacity	2.461 cc
Cylinders	5
Fuel type	Diesel
Consumption city	22.8 mpg
Consumption extra urban	36.2 mpg
Consumption combined	29.7 mpg
CO2 emission	275 g/km
CO2 label	M





Internet history

Entry 2

Date	2021-09-24
Pictures	14
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-09-23
Pictures	14
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-24
MOT pass rate	61 %
MOT passed	14
Failed MOT tests	9
Total advice items	39
Total items failed	16

MOT #23	2023-11-24 17:26
MOT test number	238758944323
Result	✓ Passed
Next expiry date	2024-11-24

MOT #22	2022-11-05 11:28
MOT test number	769982449105
Result	✓ Passed
Minor	Offside Rear Brake hose slightly damaged (1.1.12 (b) (i))
Minor	Nearside Front Brake hose slightly damaged (1.1.12 (b) (i))
Minor	Nearside Rear Brake hose slightly damaged (1.1.12 (b) (i))
Minor	Offside Front Brake hose slightly damaged (1.1.12 (b) (i))

**MOT #21**

2022-11-05 11:28

**MOT test number**

371476061386

**Result****✗ Failed****Minor** Nearside Front Brake hose slightly damaged (1.1.12 (b) (i))**Pass with rectification** Nearside Rear Outer Rear reflector defective or damaged by more than 50% of the reflecting surface (4.8.1 (a) (ii))**Minor** Nearside Rear Brake hose slightly damaged (1.1.12 (b) (i))**Minor** Offside Front Brake hose slightly damaged (1.1.12 (b) (i))**Minor** Offside Rear Brake hose slightly damaged (1.1.12 (b) (i))**MOT #20**

2021-11-25 13:15

**MOT test number**

181188580567

**Result****✓ Passed****Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**Advice** Offside Rear Seat belt buckle slightly damaged (7.1.2 (d))**MOT #19**

2021-01-12 17:16

**MOT test number**

617082572974

**Result****✓ Passed**

**MOT #18**

2020-12-17 15:08

**MOT test number**

702638753551

**Result****✗ Failed**

- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Both rear tyres worn on inner edge

**MOT #17**

2019-04-24 13:04

**MOT test number**

761802128137

**Result****✓ Passed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Minor** Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Advice** One exhaust manifold stud missing.

**MOT #16**

2019-04-18 11:45

**MOT test number**

607913131229

**Result**

✗ Failed

- Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** One exhaust manifold stud missing.
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Service brake excessively fluctuating (1.2.1 (e))
- Minor** Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Advice** MIL indicates a fault.
- Fail** Offside Front Position lamp not working (4.2.1 (a))

**MOT #15**

2018-04-18 12:16

**MOT test number**

441352640544

**Result**

✓ Passed

- Advice** ONE exhaust manifold stud broken.
- Advice** Service brake juddering slightly (3.7.C.2)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened NS&OS (3.5.1i)

**MOT #14** 2018-04-18 07:57**MOT test number** 442836431555**Result** ✗ Failed**Advice** Service brake juddering slightly (3.7.C.2)**Fail** Nearside Rear brake caliper securing device missing (3.5.1j)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened NS&OS (3.5.1i)**Advice** ONE exhaust manifold stud broken.**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #13** 2017-04-25 13:29**MOT test number** 372486140681**Result** ✓ Passed**Advice** OSR seat belt catch cover missing. Function not impaired.**Advice** Front brake disc worn, pitted or scored, but not seriously weakened NS&OS (3.5.1i)**MOT #12** 2017-04-24 10:25**MOT test number** 242311280966**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened NS&OS (3.5.1i)**Advice** OSR seat belt catch cover missing. Function not impaired.**Fail** Rear Anti-roll bar fractured (2.4.G.1)**MOT #11** 2016-04-06 13:48**MOT test number** 445791099714**Result** ✓ Passed

**MOT #10** 2016-02-02 13:24**MOT test number** 804078279544**Result** ✗ Failed

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Fail** Nearside Rear Seat belt retracting mechanism defective (5.2.5b)

**MOT #9** 2015-07-16 10:03**MOT test number** 256637995435**Result** ✓ Passed**MOT #8** 2015-07-16 10:03**MOT test number** 877207595183**Result** ✗ Failed

- Pass with rectification** Nearside Stop lamp not working (1.2.1b)

**MOT #7** 2014-08-12 15:44**MOT test number** 805634524234**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #6** 2013-12-03 09:22**MOT test number** 319407233376**Result** ✓ Passed



**MOT #5** 2012-10-03 10:20**MOT test number** 315567172436**Result** ✓ Passed**MOT #4** 2011-09-23 08:34**MOT test number** 107986761225**Result** ✓ Passed**MOT #3** 2011-09-23 08:34**MOT test number** 278666961247**Result** ✗ Failed**Pass with rectification** Rear parking brake recording little or no effort (3.7.B.6a)**MOT #2** 2010-09-28 16:18**MOT test number** 483701670299**Result** ✓ Passed**Notice** Offside front tyre wearing on inner edge**MOT #1** 2010-09-22 10:29**MOT test number** 800425560299**Result** ✗ Failed**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Notice** Offside front tyre wearing on inner edge



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
24 November 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	24 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	M
<b>Single payment (12 months)</b>	£ 695,00,-
<b>Single six month payment</b>	£ 382,25,-
<b>Total payable by 12 monthly instalments</b>	£ 729,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>GJ57PXA</b>
Plate since	2024-03-28
Current registration	 <b>GJ57PXA</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-09-25
Last registration	2023-11-24
Complete history	<a href="#">See info</a>



Registration #1	2007-09-25	26 mi
Registration #2	2010-09-22	41.935 mi
Registration #3	2010-09-28	42.495 mi
Registration #4	2011-09-23	71.363 mi
Registration #5	2012-10-03	79.052 mi
Registration #6	2013-12-03	86.252 mi
Registration #7	2014-08-12	89.478 mi
Registration #8	2015-07-16	102.382 mi
Registration #9	2016-02-02	105.463 mi
Registration #10	2016-04-06	105.494 mi
Registration #11	2017-04-24	110.353 mi
Registration #12	2017-04-25	110.387 mi
Registration #13	2018-05-01	110.387 mi
Registration #14	2018-05-01	110.387 mi
Registration #15	2018-05-01	110.387 mi
Registration #16	2018-05-01	110.387 mi
Registration #17	2018-05-01	110.387 mi
Registration #18	2018-05-01	110.387 mi
Registration #19	2018-05-01	110.387 mi
Registration #20	2018-05-01	110.387 mi
Registration #21	2018-05-01	110.387 mi
Registration #22	2018-05-01	110.387 mi
Registration #23	2018-05-01	110.387 mi
Registration #24	2018-05-01	110.387 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2230 mm
Height	1726 mm
Length	4754 mm
Wheel base	2855 mm
Max. allowed weight	2850 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	BPE 011134