



report date: 2024-03-29

General information

Make	VAUXHALL
Model	MOVANO F3500 L3H2 P/V CDTi
Colour	White
Year of manufacture	2015
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	310 Nm at 2.500 rpm
Engine capacity	2.299 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	38.7 mpg
Consumption combined	35.3 mpg
CO2 emission	211 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-11-11
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-20
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	15
Total items failed	15

MOT #12	2024-02-21 12:10
MOT test number	528315063210
Result	✓ Passed
Next expiry date	2025-02-20

MOT #11	2024-02-13 09:26
MOT test number	968750928091
Result	✗ Failed
Fail	Offside Rear Outline marker lamp adversely affected by the operation of another lamp (4.2.3 (c))
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
Fail	Offside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))

MOT #10	2022-12-06 12:31
MOT test number	301471642044
Result	✓ Passed
Advice	Brake pedal wearing smooth (1.1.2 (c))



MOT #9	2021-10-08 08:24
MOT test number	481077335796
Result	✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin Inner (1.1.13 (a) (ii))
Advice	Offside Rear Service brake binding but not excessively Slight bind (1.2.1 (f))

MOT #8	2021-10-07 15:41
MOT test number	586095461833
Result	✗ Failed
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Offside Rear Service brake binding but not excessively Slight bind (1.2.1 (f))
Advice	Offside Rear Brake pad(s) wearing thin Inner (1.1.13 (a) (ii))
Fail	Offside Side repeater not working (4.4.1 (a) (ii))
Fail	Offside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #7	2020-11-09 17:07
MOT test number	614857281152
Result	✓ Passed

MOT #6	2019-10-24 16:21
MOT test number	718166295687
Result	✓ Passed
Advice	Brake pedal wearing smooth (1.1.2 (c))
Advice	Offside Rear Bumper mountings corroded but not likely to become detached Hinge mounting bolts loose (6.1.4 (a) (i))
Advice	Offside and Nearside outline marker lamps inoperative

**MOT #5** 2019-10-24 10:45**MOT test number** 410671507043**Result** ✗ Failed**Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Offside Front Windscreen washer not working (3.5 (a))**Advice** Offside and Nearside outline marker lamps inoperative**Advice** Offside Rear Bumper mountings corroded but not likely to become detached Hinge mounting bolts loose (6.1.4 (a) (i))**Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Reversing lamp inoperative (4.6.1 (a))**Fail** Nearside Front Windscreen washer not working (3.5 (a))**Fail** Front Registration plate inscription illegible (0.1 (b))**Advice** Brake pedal wearing smooth (1.1.2 (c))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #4** 2018-10-23 13:11**MOT test number** 764532787360**Result** ✓ Passed**Advice** Offside Front Nail in tyre and slightly worn inner edge**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Power steering pump has slight seepage (2.1.5 (a))**MOT #3** 2017-10-24 16:13**MOT test number** 230472037596**Result** ✓ Passed



MOT #2	2017-10-21 09:13
MOT test number	897738058715
Result	✗ Failed
Fail	Brake pedal anti-slip provision incomplete (3.3.A.1b)
Fail	Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' cracked (8.3.1d)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #1	2016-10-25 10:19
MOT test number	538454776193
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
20 February 2025

Tax status	Valid until 1 December
Days left	216
MOT expiry date	20 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-01-01
Previous owner since	2019-01-01
Number of owners	1
Current owner since	2019-01-01
Previous owner since	2019-01-01

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 FD64XZT
Plate since	2019-01-01
Current registration	 FD64XZT
Plate since	2019-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2015-01-30
Last registration	2024-02-21
Complete history	See info



Registration #1	2015-01-30	12 mi
Registration #2	2016-10-25	48.895 mi
Registration #3	2017-10-21	75.731 mi
Registration #4	2017-10-24	76.048 mi
Registration #5	2018-10-23	102.382 mi
Registration #6	2019-10-24	115.916 mi
Registration #7	2019-10-24	115.916 mi
Registration #8	2020-05-20	121.277 mi
Registration #9	2020-05-20	121.277 mi
Registration #10	2020-05-20	121.277 mi
Registration #11	2020-05-20	121.277 mi
Registration #12	2020-05-20	121.277 mi
Registration #13	2020-05-20	121.277 mi
Registration #14	2024-02-21	121.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2470 mm
Height	2488 mm
Length	6198 mm
Kerb weight	1970 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	M9T -C140576 LWL