





report date: 2024-03-28

#### General information

Make	BMW
Model	M3
Colour	Silver
Year of manufacture	2003
Top speed	155 mph
0 - 60 mph	5.2 seconds
Gearbox	6 speed Manual

#### Engine & fuel consumption

Power	338 BHP
Max. torque	365 Nm at 4.900 rpm
Engine capacity	3.246 cc
Cylinders	6
Fuel type	Petrol
Consumption city	15.9 mpg
Consumption extra urban	33.6 mpg
Consumption combined	23.7 mpg
CO2 emission	287 g/km
CO2 label	М



CarCheck.co.uk page 1/13



report date: 2024-03-28

#### Internet history


#### Entry 1

Date 2021-07-08


Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

	_			
MO	1	hic	to	r\/
				ıv.
				. ,

MOT expiry date	2025-04-29
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	10
Total items failed	4

MOT #20	2024-04-19 14:24
MOT test number	959807973441
Result	✓ Passed
Next expiry date	2025-04-29

MOT #19	2	023-04-20 13:48
MOT test	number	102609837242
Result		✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)	)

MOT #18	2022-04-30 08:31
MOT test number	900215470684
Result	✓ Passed

MOT #17	2019-07-22 10:38
MOT test number	264345239123
Result	<b>✓</b> Passed
Advice Vehicle modified	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #16	2018-05-14 14:28

**MOT test number** 890662241909

**MOT #15** 2017-01-10 16:34

**MOT test number** 824485728479

Result 

Passed

**MOT #14** 2017-01-10 16:34

**MOT test number** 345473404116

**Result** X Failed

**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)

MOT #13 2015-11-27 14:14

**MOT test number** 452480402331

MOT #12 2014-11-21 14:36

MOT test number 615665524327

MOT #11 2013-11-12 11:50

**MOT test number** 945466113393

Notice Exhaust flange between centre section and back box cracked but not leaking exhaust gasses

**Notice** Exhaust back box mounting rubber split but still supporting system

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #10 2013-11-12 11:50 MOT test number 496556813452

Result × Failed

Notice Exhaust flange between centre section and back box cracked but not leaking exhaust gasses

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Notice Exhaust back box mounting rubber split but still supporting system

MOT #9 2012-11-13 16:38

MOT test number 159128212328

**Result** ✓ Passed

MOT #8 2012-11-10 09:53

**MOT test number** 747475312312

Result X Failed

**Fail** Front brake application uneven (3.7.B.2)

Fail Brakes imbalanced across an axle (3.7.B.5b)

MOT #7 2011-11-28 11:36

MOT test number 895382431320

Result 

Passed

**MOT #6** 2010-11-20 12:16

**MOT test number** 362164720322

**Result** ✓ Passed

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #5	2009-11-12 08:28
MOT test number	720606519398
Result	<b>✓</b> Passed
MOT #4	2008-11-05 13:30
MOT test number	462220718370
Result	✓ Passed
MOT #3	2007-11-24 10:46
MOT test number	811188427327
Result	✓ Passed
MOT #2	2006-11-20 09:49
MOT test number	132154426350
Result	✓ Passed
MOT #1	2006-08-25 17:06
MOT test number	693527736224
	4 Daggard
Result	<b>√</b> Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	29 April 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra BMW salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

More info >

# Owner history For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this BMW had different number plates. obser of plates faste since

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

### Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2003-09-01
Last registration	2024-04-19
Complete history	See info



Registration #1	2003-09-01	24 mi
Registration #2	2006-08-25	26.711 mi
Registration #3	2006-11-20	27.363 mi
Registration #4	2007-11-24	29.397 mi
Registration #5	2008-11-05	30.338 mi
Registration #6	2009-11-12	31.953 mi
Registration #7	2010-11-20	33.608 mi
Registration #8	2011-11-28	36.136 mi
Registration #9	2012-11-10	44.640 mi
Registration #10	2012-11-13	44.641 mi
Registration #11	2013-11-12	52.813 mi
Registration #12		11.117 es
Registration #13		11.177 es
Registration #14		11.117 es
Registration #15		11.177 es
Registration #16		11.117 es
Registration #17		11.177 es
Registration #18		11.117 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		77.777 46

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

#### Car features

50225	Air conditioning
50295	
0482	
0501	
0566	
0567	
60569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1702 mm
Height	2692 mm
Length	4445 mm
Wheel base	2725 mm

#### Additional information

Fuel tank capacity	63 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number Carcheck.co.uk	60743069 page 13/13