



report date: 2024-03-28

General information

Make	CITROEN
Model	RELAY 35 L3 BLUEHDI
Colour	White
Year of manufacture	2017
Top speed	93 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	44.8 mpg
Consumption combined	42.8 mpg
CO2 emission	173 g/km
CO2 label	H





MOT history

MOT expiry date	2025-03-21
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	20
Total items failed	19

MOT #8	2024-03-22 08:17
MOT test number	501340360361
Result	✓ Passed
Next expiry date	2025-03-21
Advice	All - side marker lamps not working
Advice	Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #7**

2024-03-08 16:33

MOT test number

533516269271

Result**✗ Failed****Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** All - side marker lamps not working**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Power steering component insecure pipe - bracket broken by crankshaft pulley (2.1.5 (d) (i))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear wheel noisy when rotated - possibly brake component squealing**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure out of shape / flat spot and perished (5.2.3 (d) (ii))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #6**

2023-03-21 16:32

MOT test number

575747135444

Result**✓ Passed****Advice** Nearside side repeater lens missing**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**Advice** Coolant leak

**MOT #5**

2023-03-08 16:49

MOT test number

307139747568

Result**✗ Failed****Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Handbrake lever bracket bent**Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Minor** Registration plate lamp insecure (4.7.1 (c) (i))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Coolant leak**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Parking brake lever inoperative (1.1.6 (d))**Advice** Both tail lamp lens damaged**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Minor** Registration plate lamp throwing direct white light to the rear (4.7.1 (a))**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**Fail** Offside Rear Outline marker lamp missing (4.2.1 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside side repeater lens missing

**MOT #4** 2022-03-16 17:12**MOT test number** 860642216829**Result** ✓ Passed**Advice** Exhaust bent**Advice** Side repeater lens missing**MOT #3** 2021-02-25 13:44**MOT test number** 294232277336**Result** ✓ Passed**MOT #2** 2021-02-17 11:50**MOT test number** 633191268537**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Registration plate lamp missing in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #1** 2020-06-23 05:15**MOT test number** 621787666627**Result** ✓ Passed**Advice** COVID-19 6 MONTH EXTENSION



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
21 March 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	21 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	DK17DSX
Plate since	2019-03-28
Current registration	DK17DSX
Plate since	2019-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-07-01
Last registration	2024-03-22
Complete history	See info



Registration #1	2017-07-01	17 mi
Registration #2	2021-02-17	21.792 mi
Registration #3	2021-02-25	21.795 mi
Registration #4	2022-03-16	38.761 mi
Registration #5	2023-03-22	39.277 mi
Registration #6	2023-03-22	39.277 mi
Registration #7	2023-03-22	39.277 mi
Registration #8	2024-03-22	39.277 mi

More info >



Safety ratings

NCAP rating	★★★★
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Dimensions & weight

Width	2770 mm
Height	2153 mm
Length	5843 mm
Kerb weight	1655 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Number of axles	2
Engine number	DYZZ4044583