



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VERSO VVTI T SPIRIT
Colour	Black
Year of manufacture	2006
Top speed	115 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	133 BHP
Max. torque	170 Nm at 4.800 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.3 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.2 mpg
CO2 emission	184 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-01-06
Pictures	4
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-06
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	40
Total items failed	7

MOT #18	2023-09-07 11:26
---------	------------------

MOT test number	917829211349
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-09-06
------------------	------------

- Minor

Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice

Rear Integral body structure is corroded but structural rigidity is not significantly reduced Both sides (6.1.1 (c) (i))
- Minor

Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice

Rear Parking brake lever defective but can be satisfactorily operated Both sides needed slightly adjustment (1.1.6 (d))
- Minor

Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Rear Brake pipe corroded, covered in grease or other material Both sides (1.1.11 (c))
- Advice

Nearside Front Macpherson strut damaged but not seriously weakened (5.3.3 (b) (i))

**MOT #17**

2023-09-07 10:03

**MOT test number**

266804135728

**Result****✗ Failed****Advice** Nearside Front Macpherson strut damaged but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Rear Integral body structure is corroded but structural rigidity is not significantly reduced Both sides (6.1.1 (c) (i))**Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Rear Parking brake lever defective but can be satisfactorily operated Both sides needed slightly adjustment (1.1.6 (d))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))**Fail** Offside Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))**Fail** Nearside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords And getting worn on edge (5.2.3 (d) (i))**Advice** Offside Rear Nail in tyre**Advice** Rear Brake pipe corroded, covered in grease or other material Both sides (1.1.11 (c))**Minor** Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #16**

2022-08-02 09:00

**MOT test number**

208831931429

**Result****✓ Passed****Advice** Parking brake lever defective but can be satisfactorily operated excessive travel hand brake lever (1.1.6 (d))**Advice** Nearside Front Upper Macpherson strut mounting damaged but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** N/s/rear door and rear wing damaged

**MOT #15** 2021-08-17 08:02**MOT test number** 437217585323**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #14** 2020-08-17 08:49**MOT test number** 749329441661**Result** ✓ Passed**Advice** Handbrake near end of reserve travel.**MOT #13** 2019-08-20 09:01**MOT test number** 762123306750**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #12** 2018-08-20 13:48**MOT test number** 765759326895**Result** ✓ Passed**MOT #11** 2017-07-24 08:03**MOT test number** 199465515386**Result** ✓ Passed

**MOT #10** 2016-08-10 09:51**MOT test number** 768399187554**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear tyre at 2.5mm**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2015-07-24 09:31**MOT test number** 157835805291**Result** ✓ Passed**Notice** Offside rear tyre tread cracked**MOT #8** 2014-08-13 09:20**MOT test number** 605975424253**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2013-08-21 09:26**MOT test number** 376783733238**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2012-08-20 15:12**MOT test number** 475943632241**Result** ✓ Passed

**MOT #5** 2011-08-10 10:00**MOT test number** 778102221228**Result** ✓ Passed**Notice** Both front and n/s/r tyres almost bald on edges**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #4** 2010-08-20 16:49**MOT test number** 530802630236**Result** ✓ Passed**MOT #3** 2010-08-20 12:17**MOT test number** 921962230200**Result** ✗ Failed**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #2** 2009-08-18 12:23**MOT test number** 933990339279**Result** ✓ Passed**Notice** NAIL IN N/S/R TYRE**MOT #1** 2009-08-18 12:23**MOT test number** 233480839264**Result** ✗ Failed**Notice** NAIL IN N/S/R TYRE**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
6 September 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	6 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	<b>YY06ZXP</b>
Plate since	2019-06-28
Current registration	<b>YY06ZXP</b>
Plate since	2019-06-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-08-22
Last registration	2023-09-07
Complete history	<a href="#">See info</a>



Registration #1	2006-08-22	26 mi
Registration #2	2009-08-18	25.277 mi
Registration #3	2010-08-20	30.825 mi
Registration #4	2010-08-20	30.825 mi
Registration #5	2011-08-10	36.320 mi
Registration #6	2012-08-20	42.155 mi
Registration #7	2013-08-21	47.639 mi
Registration #8	2014-08-13	53.018 mi
Registration #9	2015-07-24	58.911 mi
Registration #10	2016-08-10	65.957 mi
Registration #11	2016-08-10	65.957 mi
Registration #12	2016-08-10	65.957 mi
Registration #13	2016-08-10	65.957 mi
Registration #14	2016-08-10	65.957 mi
Registration #15	2016-08-10	65.957 mi
Registration #16	2016-08-10	65.957 mi
Registration #17	2016-08-10	65.957 mi
Registration #18	2016-08-10	65.957 mi
Registration #19	2016-08-10	65.957 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1620 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1365 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	1ZZE466915