



report date: 2024-03-29

General information

Make	FIAT
Model	500 LOUNGE
Colour	Red
Year of manufacture	2017
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	110 g/km
CO2 label	B






Internet history

Entry 4



Date	2021-07-10
Pictures	20
Listing price	View report



source: [heycar.co.uk](https://www.heycar.co.uk)

Entry 3




Date	2021-06-25
Pictures	19
Listing price	View report



source: [yesauto.com](https://www.yesauto.com)

Entry 2

Date	2021-06-23
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1



Date	2021-05-12
------	------------

Pictures

23

Listing price

[View report](#)



source: yesauto.com

**MOT history**

MOT expiry date	2024-07-21
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #5	2023-07-20 13:13
MOT test number	651425686456
Result	✓ Passed
Next expiry date	2024-07-21
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #4	2022-07-22 13:15
MOT test number	520513331227
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge at 3mm also cracking on tread and worn on edges - 185/55R15 (5.2.3 (e))
Advice	Exhaust system corroded
Advice	Offside Front Play in steering rack inner joint(s)
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
Advice	Engine sump corroded
Advice	Offside Rear Tyre slightly damaged/cracking or perishing cracking on tread (5.2.3 (d) (ii))

**MOT #3** 2022-07-22 11:59**MOT test number** 552663656523**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking on tread (5.2.3 (d) (ii))**Advice** Exhaust system corroded**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge at 3mm also cracking on tread and worn on edges - 185/55R15 (5.2.3 (e))**Advice** Engine sump corroded**Advice** Offside Front Play in steering rack inner joint(s)**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**MOT #2** 2021-05-21 15:12**MOT test number** 573916476026**Result** ✓ Passed**MOT #1** 2020-06-11 11:46**MOT test number** 283355417347**Result** ✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	PL17KRE
Plate since	2024-03-29
Current registration	PL17KRE
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-06-30
Last registration	2023-07-20
Complete history	See info



Registration #1	2017-06-30	13 mi
Registration #2	2020-06-11	14.902 mi
Registration #3	2020-06-11	15.277 mi
Registration #4	2021-05-21	18.207 mi
Registration #5	2020-06-11	15.277 mi
Registration #6	2020-06-11	15.277 mi
Registration #7	2020-06-11	15.277 mi
Registration #8	2020-06-11	15.277 mi
Registration #9	2020-06-11	15.277 mi
Registration #10	2020-06-11	15.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	66%
Children	49%
Pedestrian	53%
Safety systems	27%
Overall rating	52%
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3571 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1345 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2

Engine number	2181262
---------------	---------