



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE DESIGN TSI
Colour	Silver
Year of manufacture	2015
Top speed	129 mph
0 - 100 km/h	8.3 seconds
0 - 60 mph	8.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 kW / 161 HP / 158 BHP
Max. torque	240 Nm at 1.500 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg
CO2 emission	153 g/km
CO2 label	G






Internet history

Entry 1

Date	2022-07-23
Pictures	50
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-05-08
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	6
Total items failed	3

MOT #9	2024-04-19 14:44
MOT test number	383119079373
Result	✓ Passed
Next expiry date	2025-05-08

MOT #8	2024-04-19 08:09
MOT test number	236050066727
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2023-05-09 09:39
MOT test number	778850785645
Result	✓ Passed
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #6	2022-04-29 12:22
MOT test number	422872334126
Result	✓ Passed

**MOT #5** 2022-04-29 12:22**MOT test number** 686449234730**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #4** 2021-05-01 13:23**MOT test number** 897250107706**Result** ✓ Passed**MOT #3** 2020-01-20 10:20**MOT test number** 384944174648**Result** ✓ Passed**MOT #2** 2019-01-14 12:47**MOT test number** 145074421927**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**MOT #1** 2018-01-09 13:23**MOT test number** 751319922265**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre In shoulder NOT REPAIRABLE



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
8 May 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	8 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-28
Current registration	 XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-01-12
Last registration	2024-04-19
Complete history	See info



Registration #1	2015-01-12	16 mi
Registration #2	2018-01-09	13.520 mi
Registration #3	2019-01-14	24.013 mi
Registration #4	2020-01-20	28.085 mi
Registration #5	2021-05-01	29.469 mi
Registration #6	2022-04-29	30.542 mi
Registration #7	2023-05-20	31.277 mi
Registration #8	2023-05-20	31.277 mi
Registration #9	2023-05-20	31.277 mi
Registration #10	2023-05-20	31.277 mi
Registration #11	2023-05-20	31.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	90%
Pedestrian	53%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2021 mm
Height	1486 mm
Length	4278 mm
Wheel base	2537 mm
Kerb weight	1359 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CTHD183214