



report date: 2024-03-29

General information

Make	VOLVO
Model	V60 D5 R-DESIGN LUX NAV
Colour	Silver
Year of manufacture	2014
Top speed	143 mph
0 - 60 mph	7.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	212 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	120 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-19
Pictures	73
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-26
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	14
Total items failed	8

MOT #10	2024-03-26 09:39
MOT test number	188765146369
Result	✓ Passed
Next expiry date	2025-03-26
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #9	2023-03-18 12:33
MOT test number	225101014376
Result	✓ Passed
Advice	Cultch pedal rubber missing
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**MOT #8**

2023-03-18 09:52

MOT test number

403072786955

Result

✗ Failed

- Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))
- Fail** Offside Front Headlamp aim too low (4.1.2 (a))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Clutch pedal rubber missing
- Fail** Front Service brake imbalanced across an axle (1.2.1 (b) (i))
- Fail** Nearside Front Headlamp aim too low (4.1.2 (a))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #7

2022-03-23 10:01

MOT test number

217337163634

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

MOT #6

2021-03-04 16:11

MOT test number

744288756047

Result

✓ Passed

- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #5** 2020-03-17 10:35**MOT test number** 249809850733**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front centre washer jet missing screen**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** N/s/f door sticks and difficult to open**MOT #4** 2019-03-20 13:56**MOT test number** 859380314230**Result** ✓ Passed**MOT #3** 2018-03-27 14:37**MOT test number** 647284854510**Result** ✓ Passed**MOT #2** 2017-02-06 11:36**MOT test number** 112911617571**Result** ✓ Passed**MOT #1** 2017-02-06 10:15**MOT test number** 154655971269**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
26 March 2025

Tax status	Valid until 1 July
Days left	62
MOT expiry date	26 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	OU64EYH
Plate since	2019-03-29
Current registration	OU64EYH
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-12-15
Last registration	2024-03-26
Complete history	See info



Registration #1	2014-12-15	22 mi
Registration #2	2017-02-06	70.802 mi
Registration #3	2017-02-06	70.802 mi
Registration #4	2018-03-27	91.756 mi
Registration #5	2019-03-20	109.746 mi
Registration #6	2020-03-17	123.079 mi
Registration #7	2020-03-20	123.079 mi
Registration #8	2020-03-20	123.079 mi
Registration #9	2020-03-20	123.079 mi
Registration #10	2020-03-20	123.079 mi
Registration #11	2020-03-20	123.079 mi
Registration #12	2020-03-20	123.079 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1680 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1426568