





General informationMakeVAUXHALLModelVIVARO L2H1 2900 CDTI ECOFLEX S/SColourWhiteYear of manufacture2017Gearbox6 speed Manual

Engine & fuel consumption

| Power | 94 BHP | 0 < 101 A |
|-------------------------|---------------------|-------------------------------------|
| Max. torque | 260 Nm at 1.500 rpm | 101 - 120 ^B _C |
| Engine capacity | 1.598 cc | 121 - 140 E |
| Cylinders | 4 | 141 - 165 F LABE |
| Fuel type | Diesel | 166 - 185 H |
| Consumption city | 38.7 mpg | 186 - 225 J |
| Consumption extra urban | 48.7 mpg | 225+ L |
| Consumption combined | 44.8 mpg | |
| CO2 emission | 164 g/km | |
| CO2 label | G | |





Internet history

| Entry 1 | |
|---------------|-------------|
| Date | 2021-10-20 |
| Pictures | 2 |
| Listing price | View report |





source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-10-18 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 5 |
| Failed MOT tests | 0 |
| Total advice items | 7 |
| Total items failed | 0 |

| MOT #5 | 2023-10-02 10:01 |
|--|------------------|
| MOT test number | 624643863505 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-18 |
| Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b)) | |

| MOT #4 | 2022-10-04 07:57 |
|-----------------|------------------|
| MOT test number | 497058208140 |
| Result | ✓ Passed |

| MOT #3 | 2021-10-19 12:36 |
|---|------------------|
| MOT test number | 437898760077 |
| Result | ✓ Passed |
| Advice Nearside Front Play in steering rack inner joint(s) | |
| Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) | |





| MOT #2 | 2020-12-17 09:45 |
|--|------------------|
| MOT test number | 966735442941 |
| Result | Passed |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge 205/65/16c (5.2.3 (e)) | |
| Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) | |
| | |

| MOT #1 | 2020-06-18 05:10 |
|-----------------------------------|------------------|
| MOT test number | 935743675812 |
| Result | ✓ Passed |
| Advice COVID-19 6 MONTH EXTENSION | |



Tax & MOT check

| ✓ Taxed | ✓ MOT Expires: |
|-------------------------------|---|
| 1 November 2024 Tax status | 18 October 2024 Valid until 1 November |
| Days left | 187 |
| MOT expiry date | 18 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 320,00,- |
| Standard rate (6 months) | £ 176,00,- |





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------|
| Date | FEED O |
| Category | A RANPE |
| Туре | |
| Damage 2 | AMPLE |
| Date | |
| Category | AMPLE |
| Туре | |

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ********** | |
|--|-------------|
| ********* | |
| | |
| | |
| ********** | |
| ******** | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VAUXHALL had different number plates. | |
| | |
| Number of plates | , |
| Rumber of plates Current registration | |
| Rumber of plates Current registration Fals since | |
| Rumber of plates Current registration Fate since Current registration | |
| Rumber of plates Correct registration Plate since Correct registration Plate since | 1000-20-20 |





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2017-06-26 |
| Last registration | 2023-10-02 |
| Complete history | See info |



| Registration #1 | 2017-06-26 | 16 mi |
|-----------------|------------|------------|
| Registration #2 | 2020-12-17 | 120.177 mi |
| Registration #3 | 2021-10-19 | 138.838 mi |
| Registration #4 | | 11.117 esi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | |

More info \rightarrow





Safety ratings

| NCAP rating | **** | Junes Ca |
|----------------|------------------------|----------|
| Adult | 52% | EURO |
| Children | 91% | |
| Pedestrian | 53% | + |
| Safety systems | 57% | |
| Overall rating | 61% | |
| Video | <u>see crash video</u> | |



| Dimensions & weight | |
|------------------------|---------------------|
| Width | 2283 mm |
| Height | 1971 mm |
| Length | 5398 mm |
| Kerb weight | 1750 kg |
| Max. allowed weight | 3030 kg |
| Additional information | |
| Fuel tank capacity | 80 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 3 |
| Engine number | R9M MJ - C068517LWX |