



TOYOTA

R230KGG

report date: 2024-03-28

General information

Make	TOYOTA
Model	MR2
Colour	Red
Year of manufacture	-
Gearbox	-

Engine & fuel consumption

Fuel type	Petrol
-----------	--------





LABEL UNKNOWN



Internet history

Entry 2

Date	2022-12-20
Pictures	49
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2022-02-11
Pictures	12
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #15</b>	2023-05-15 09:49
<b>MOT test number</b>	340449701475
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-05-14

<b>MOT #14</b>	2023-05-12 11:15
<b>MOT test number</b>	617526339390
<b>Result</b>	✗ Failed

- Fail** Nearside Outer Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting Sill (6.2.2 (d) (i))
- Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Offside Outer Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting Sill (6.2.2 (d) (i))
- Fail** Brake lever has abnormal movement of levers indicating excessive wear or maladjustment (1.1.15 (f))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

<b>MOT #13</b>	2022-10-18 15:48
<b>MOT test number</b>	229814724759
<b>Result</b>	✓ Passed

- Advice** Offside Rear Outer Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2022-10-13 14:12

**MOT test number**

676199949466

**Result****✗ Failed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength arch (5.3.6 (a) (i))**Advice** Offside Rear Outer Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))**Fail** Emissions not tested excessive blue smoke (8.2.1.2 (d))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength arch (5.3.6 (a) (i))**Fail** Offside Parking brake inoperative on one side (1.4.1 (a))**MOT #11**

2021-10-14 17:03

**MOT test number**

189544600845

**Result****✓ Passed****Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Minor** Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt both sides (2.1.3 (g) (i))**MOT #10**

2020-09-17 08:15

**MOT test number**

805079184479

**Result****✓ Passed****MOT #9**

2019-10-17 14:36

**MOT test number**

977493654389

**Result****✓ Passed**



MOT #8

2019-10-16 15:21

MOT test number

679967962353

Result

✗ Failed

Fail

Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #7

2010-01-11 12:45

MOT test number

521391310021

Result

✓ Passed

Notice

Front brakes pull to nearside

MOT #6

2010-01-06 16:35

MOT test number

962156900059

Result

✗ Failed

Fail

Nearside Side repeater missing (1.4.A.2b)

Fail

Front registration plate missing (6.3.1a)

Fail

Front brake application uneven (3.7.B.2)

Fail

Nearside Front Direction indicators not working (1.4.A.2c)

Fail

Nearside front brake binding (3.7.B.1)



MOT #5	2009-09-17 16:55
MOT test number	674400069219
Result	✗ Failed
Fail	Nearside Front Side repeater missing (1.4.A.2b)
Fail	Nearside front brake binding (3.7.B.1)
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Fail	Front registration plate missing (6.3.1a)
Fail	Exhaust has a major leak of exhaust gases (7.1.2)
Fail	Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
Fail	Brakes imbalanced across an axle (3.7.B.5b)
Fail	Horn not working (1.6.2a)

MOT #4	2008-08-07 09:31
MOT test number	632460028294
Result	✓ Passed
Advice	Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
Advice	Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
Advice	Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**MOT #3** 2008-08-04 13:03**MOT test number** 361897418494**Result** ✗ Failed

- Fail** Offside Front Brake hose excessively deteriorated (3.6.B.4d)
- Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Offside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

**MOT #2** 2007-06-12 11:14**MOT test number** 442563867177**Result** ✓ Passed

- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Notice** Offside front wiper blade split but still clearing the windscreen effectively
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #1** 2006-04-29 12:17**MOT test number** 920869616184**Result** ✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	R230KGG
Plate since	2023-03-28
Current registration	R230KGG
Plate since	2023-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	1998-11-01
Last registration	2023-05-15
Complete history	<a href="#">See info</a>



Registration #1	1998-11-01	12 mi
Registration #2	2006-04-29	18.789 mi
Registration #3	2007-06-12	19.116 mi
Registration #4	2008-08-04	27.073 mi
Registration #5	2008-08-07	27.083 mi
Registration #6	2009-09-17	27.154 mi
Registration #7	2010-01-06	27.198 mi
Registration #8	2010-01-11	27.209 mi
Registration #9	2019-10-16	28.858 mi
Registration #10	2019-10-16	28.858 mi
Registration #11	2019-10-16	28.858 mi
Registration #12	2019-10-16	28.858 mi
Registration #13	2019-10-16	28.858 mi
Registration #14	2019-10-16	28.858 mi
Registration #15	2019-10-16	28.858 mi
Registration #16	2019-10-16	28.858 mi
Registration #17	2019-10-16	28.858 mi
Registration #18	2019-10-16	28.858 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Engine number NOT STATED