



PEUGEOT




report date: 2024-03-28

General information

Make	PEUGEOT
Model	BOXER HDI 335 L3H2 PROFESSIONAL P/V
Colour	White
Year of manufacture	2015
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	38.2 mpg
CO2 emission	195 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-11-04
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-02-27
MOT pass rate	45 %
MOT passed	5
Failed MOT tests	6
Total advice items	38
Total items failed	0

MOT #11	2023-02-28 11:34
MOT test number	145972015620
Result	✓ Passed
Next expiry date	2024-02-27
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #10	2023-02-22 13:41
MOT test number	813086622417
Result	✗ Failed
MAJOR	Nearside Front Service brake excessively binding (1.2.1 (f))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))
MAJOR	Registration plate lamp inoperative in the case of a single lamp or all lamps Both (4.7.1 (b) (ii))
MAJOR	Nearside Rear All direction indicators incorrect colour (4.4.3 (a))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
MAJOR	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
MAJOR	Windscreen washer not working Both (3.5 (a))

**MOT #9** 2023-01-31 15:16**MOT test number** 729716434434**Result** ✗ Failed**MAJOR** Windscreen washer not working (3.5 (a))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Offside Headlamp aim not tested dip beam not working (4.1.2 (b))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**MAJOR** Exhaust emissions exceed manufacturer's specified limit 0.51 (8.2.2.2 (a))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Parking brake inoperative on one side (1.4.1 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Items removed from driver's view prior to test**MOT #8** 2022-01-12 11:10**MOT test number** 217590569617**Result** ✓ Passed**MOT #7** 2021-02-15 15:21**MOT test number** 197116449398**Result** ✓ Passed

**MOT #6** 2021-02-12 12:03**MOT test number** 889001146025**Result** ✗ Failed**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MAJOR** Fuel system component leaking diesel around tank (6.1.3 (b) (i))**MOT #5** 2019-06-26 16:27**MOT test number** 661848433328**Result** ✓ Passed**MOT #4** 2019-06-25 15:15**MOT test number** 495021539884**Result** ✗ Failed**Advice** Brake pad(s) wearing thin fronts (1.1.13 (a) (ii))**Advice** Nearside Rear tyre cracking up in treads also wearing outer edge slightly**MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front slight damage outer sidewalls of tyre**Advice** Offside Rear tyre cracking up in treads**MAJOR** Windscreen wiper does not clear the windscreen effectively both fronts (3.4 (b) (ii))**MOT #3** 2018-06-19 13:16**MOT test number** 668090213177**Result** ✓ Passed**Advice** Nearside Sill damaged but not structurally weakened



MOT #2	2018-06-19 12:48
MOT test number	922702789273
Result	✗ Failed
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Nearside Sill damaged but not structurally weakened

MOT #1	2018-05-30 11:29
MOT test number	629351922698
Result	✗ Failed
Advice	Nearside Rear Nail in tyre
Advice	Nearside Sill damaged but not structurally weakened
MAJOR	Windscreen damaged and affecting the driver's view of an obligatory external mirror (3.2 (a) (ii))
DANGEROUS	Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✗
MOT
Expired:
27 February 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	27 February 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	YB15KHA
Plate since	2015-06-29
Current registration	YB15KHA
Plate since	2015-06-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-06-26
Last registration	2023-02-28
Complete history	See info



Registration #1	2015-06-26	24 mi
Registration #2	2018-05-30	94.812 mi
Registration #3	2018-06-19	96.003 mi
Registration #4	2018-06-19	96.003 mi
Registration #5	2019-06-25	110.205 mi
Registration #6	2019-06-26	110.205 mi
Registration #7	2021-02-12	110.303 mi
Registration #8	2022-05-28	110.303 mi
Registration #9	2022-05-28	110.303 mi
Registration #10	2022-05-28	110.303 mi
Registration #11	2022-05-28	110.303 mi
Registration #12	2022-05-28	110.303 mi
Registration #13	2022-05-28	110.303 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	TRJA0875452