



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	1007 S
Colour	Silver
Year of manufacture	-
Top speed	107 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	87 BHP
Max. torque	133 Nm at 3.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-10
Pictures	5
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #17</b>	2021-09-21 12:28
<b>MOT test number</b>	213066701011
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-09-24
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

<b>MOT #16</b>	2020-09-25 16:12
<b>MOT test number</b>	916267274525
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

<b>MOT #15</b>	2019-09-20 09:39
<b>MOT test number</b>	563873064196
<b>Result</b>	✓ Passed
<b>Minor</b>	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Rear Exhaust mounting defective (6.1.2 (a))

**MOT #14** 2019-09-20 09:26**MOT test number** 718982873430**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Front Position lamp not working both (4.2.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2018-09-05 10:02**MOT test number** 803397879868**Result** ✓ Passed

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #12** 2018-09-05 10:02**MOT test number** 857267182402**Result** ✗ Failed

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Pass with rectification** Front Windscreen washer provides insufficient washer liquid washer fluid topped up (3.5 (a))

**MOT #11** 2017-08-09 09:33**MOT test number** 796475667476**Result** ✓ Passed**MOT #10** 2017-08-09 09:33**MOT test number** 980786839651**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #9** 2016-07-14 13:13**MOT test number** 637632949407**Result** ✓ Passed**MOT #8** 2015-07-25 15:02**MOT test number** 937436905275**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #7** 2014-07-29 10:39**MOT test number** 415390214296**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear exhaust bracket corroded



<b>MOT #6</b>	2013-08-03 12:04
---------------	------------------

<b>MOT test number</b>	116665513280
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2012-07-28 10:34
---------------	------------------

<b>MOT test number</b>	239620512233
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2011-08-08 17:18
---------------	------------------

<b>MOT test number</b>	315470421469
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2010-03-03 12:26
---------------	------------------

<b>MOT test number</b>	490152460089
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2010-03-03 12:26
---------------	------------------

<b>MOT test number</b>	554352160023
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Pass with rectification</b>	Nearside Headlamp aim too high (1.8)
--------------------------------	--------------------------------------

<b>Pass with rectification</b>	Offside Headlamp aim too high (1.8)
--------------------------------	-------------------------------------

<b>MOT #1</b>	2009-03-18 16:24
---------------	------------------

<b>MOT test number</b>	414737379027
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Nearside Front brake drum slightly pitted (3.5.1h)
---------------	--

<b>Advice</b>	Offside Front brake drum slightly pitted (3.5.1h)
---------------	---



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	EN06PHX
Plate since	2024-03-29
Current registration	EN06PHX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-06-20
Last registration	2021-09-21
Complete history	<a href="#">See info</a>



Registration #1	2006-06-20	21 mi
Registration #2	2009-03-18	15.773 mi
Registration #3	2010-03-03	19.696 mi
Registration #4	2011-08-08	23.162 mi
Registration #5	2012-07-28	24.088 mi
Registration #6	2013-08-03	25.686 mi
Registration #7	2014-07-29	29.036 mi
Registration #8	2015-07-25	33.494 mi
Registration #9	2016-07-14	34.534 mi
Registration #10	2016-07-14	35.574 mi
Registration #11	2016-07-14	36.614 mi
Registration #12	2016-07-14	37.654 mi
Registration #13	2016-07-14	38.694 mi
Registration #14	2016-07-14	39.734 mi
Registration #15	2016-07-14	40.774 mi
Registration #16	2016-07-14	41.814 mi
Registration #17	2016-07-14	42.854 mi
Registration #18	2016-07-14	43.894 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1757 mm
Height	1530 mm
Length	4211 mm
Wheel base	2608 mm
Kerb weight	1249 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FE030215387