





report date: 2024-03-29

### General information

| Make                | MINI           |
|---------------------|----------------|
| Model               | COOPER D ONE D |
| Colour              | Black          |
| Year of manufacture | 2013           |
| Top speed           | 114 mph        |
| 0 - 60 mph          | 11.4 seconds   |
| Gearbox             | 6 speed Manual |

### Engine & fuel consumption

| Power                   | 90 BHP              |
|-------------------------|---------------------|
| Max. torque             | 215 Nm at 1.750 rpm |
| Engine capacity         | 1.598 сс            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 67.3 mpg            |
| Consumption extra urban | 80.7 mpg            |
| Consumption combined    | 74.3 mpg            |
| CO2 emission            | 99 g/km             |
| CO2 label               | A                   |



CarCheck.co.uk page 1/12



report date: 2024-03-29

### Internet history

#### Entry 2

Date 2023-01-20

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

| Date     | 2022-04-30 |
|----------|------------|
| Pictures | 35         |

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

2023-02-01 11:44

### MOT history

MOT #10

| MOT expiry date    | 2025-02-01 |
|--------------------|------------|
| MOT pass rate      | 69 %       |
| MOT passed         | 9          |
| Failed MOT tests   | 4          |
| Total advice items | 14         |
| Total items failed | 6          |

| MOT #13          | 2024-01-30 16:06 |
|------------------|------------------|
| MOT test number  | 581654614907     |
| Result           | <b>✓</b> Passed  |
| Next expiry date | 2025-02-01       |

| MOT #12   | 2024-01-26 13:41       |
|---|------------------------|
| MOT test number   | 389584706310           |
| Result  | <b>X</b> Failed        |
| Minor  (i))  Offside Registration plate lamp inoperative in the case of multiple lamps or light (ii)) | ght sources (4.7.1 (b) |
| Fail Nearside Front Shock absorbers has negligible damping effect also weaping oil                    | (5.3.2 (d))            |
| Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))                                       |                        |

| MOT #11         | 2023-02-02 12:55 |
|-----------------|------------------|
| MOT test number | 105045340129     |
| Result          | ✓ Passed         |

| MOT te   | est number 160995001937 |
|--|-------------------------|
| Result   | <b>▼</b> Failed         |
| Fail Front Suspension arm pin or bush excessively worn rear bushes on front wishbones worn excessively |                         |
| (5.3.4 (a) (i))  |                         |

CarCheck.co.uk page 3/12



**Advice** 

Nearside Rear tyre perished

PN13KWD

report date: 2024-03-29

**MOT** #9 2022-05-05 11:32 947336342379 **MOT** test number Result ✓ Passed **MOT** #8 2021-11-18 15:47 **MOT** test number 802592423304 Result ✓ Passed Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Drivers side washer jet not working Advice Offside Rear tyre perished Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Front tyre perished

**MOT #7** 2021-11-18 11:39 **MOT test number** 642083385625 × Failed Result Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Front tyre perished **Advice** Nearside Rear tyre perished Advice Drivers side washer jet not working **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Rear tyre perished

CarCheck.co.uk page 4/12



report date: 2024-03-29

| MOT #6          | 2020-03-19 15:31 |
|-----------------|------------------|
| MOT test number | 516159975451     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #5          | 2019-03-08 11:59 |
| MOT test number | 502204423310     |
| Result          | <b>√</b> Passed  |
|                 |                  |

MOT #4 2019-03-05 17:46
MOT test number 265190188541

**Result** X Failed

Fail Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Exhaust has a major leak of exhaust gases (6.1.2 (a))

| 2018-03-26 08:54 |
|------------------|
| 167648034454     |
| ✓ Passed         |
|                  |
| 2017-03-27 11:26 |
| 310092334030     |
| √ Passed         |
|                  |

| MOT #1  | 2016-02-24 10:13 |
|---|------------------|
| MOT test number                                 | 433024553939     |
| Result  | <b>✓</b> Passed  |
| Advice Front Brake pad(s) wearing thin (3.5.1g) |                  |

CarCheck.co.uk page 5/12



report date: 2024-03-29

#### Tax & MOT check



| Tax status       | Valid until 1 February |
|------------------|------------------------|
| Days left        | 277                    |
| MOT expiry date  | 1 February 2025        |
| Full MOT history | See MOT history        |

#### Tax calculation

| Vehicle class                           | 49             |
|---|----------------|
| Band                                    | A              |
| Single payment (12 months)              | £ 0,00,-       |
| Single six month payment                | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

# Owner history

| For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <a href="here">here</a> . |             |
|---|-------------|
|   |             |
|   |             |
|   |             |
|   |             |
| ********  |             |
|   |             |
| ***************************************   |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this MINI had different number plates.   |             |
| Number of plates  | ,           |
| Current registration  | UK UK       |
| Plate since   |             |
| Current registration  | NK NK       |
| Plate since   |             |
|   | More info > |

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

**Contact info** 

More info >

CarCheck.co.uk page 10/12




report date: 2024-03-29

# Mileage check

Registration #16

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 16         |
| First mileage registration | 2013-03-13 |
| Last registration          | 2024-01-30 |
| Complete history           | See info   |



| Registration #1  | 2013-03-13 | 6 mi      |
|------------------|------------|-----------|
| Registration #2  | 2016-02-24 | 36.083 mi |
| Registration #3  | 2017-03-27 | 47.599 mi |
| Registration #4  | 2018-03-26 | 55.315 mi |
| Registration #5  | 2019-03-05 | 59.730 mi |
| Registration #6  | 2019-03-08 | 59.732 mi |
| Registration #7  | 2020-03-19 | 61.207 mi |
| Registration #8  | 2021-11-18 | 64.140 mi |
| Registration #9  |            | 11.777 es |
| Registration #10 |            | 11.777 es |
| Registration #11 |            | 11.777 es |
| Registration #12 |            | 11.777 es |
| Registration #13 |            | 11.777 es |
| Registration #14 |            | 11.777 es |
| Registration #15 |            | 11.777 es |
|                  |            |           |

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 11/12



report date: 2024-03-29

# Car features

| 50225 | Air conditionin |
|-------|-----------------|
| 60295 |                 |
| 60482 |                 |
| 60501 |                 |
| 60566 |                 |
| 0567  |                 |
| 60569 |                 |

# Safety ratings

| NCAP rating | ****            |
|-------------|-----------------|
| Video       | see crash video |



# Dimensions & weight

| Width               | 1683 mm |
|---------------------|---------|
| Height              | 1407 mm |
| Length              | 3723 mm |
| Wheel base          | 2467 mm |
| Kerb weight         | 1090 kg |
| Max. allowed weight | 1540 kg |

# Additional information

| Fuel tank capacity                | 40               |
|-----------------------------------|------------------|
| Fuel delivery                     | Direct Injection |
| Number of doors                   | 3                |
| Number of seats<br>CarCheck.co.uk | 4 page 12/12     |

Number of axles 2

**Engine number** 70728575