



GJ57VMX

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE SPORT TSI 140
Colour	Red
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	220 Nm at 1.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg





Internet history

Entry 2

Date	2021-11-11
Pictures	7
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-11-10
Pictures	7
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #16	2021-11-24 14:07
MOT test number	794372884277
Result	✓ Passed
Next expiry date	2022-11-23

MOT #15	2021-08-28 08:55
MOT test number	459793146178
Result	✓ Passed

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Front Play in steering rack inner joint(s)

MOT #14	2021-08-27 11:19
MOT test number	472628780295
Result	✗ Failed

Advice Nearside Front Play in steering rack inner joint(s)

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Fail Offside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Nearside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #13	2020-09-01 10:36
MOT test number	611445129560
Result	✓ Passed

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #12** 2019-09-06 12:50**MOT test number** 526638112921**Result** ✓ Passed

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Hole in exhaust/corroded

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #11 2018-09-15 08:01**MOT test number** 264119509906**Result** ✓ Passed**MOT #10** 2017-09-13 13:17**MOT test number** 617970669944**Result** ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #9 2016-09-14 12:26**MOT test number** 106033165999**Result** ✓ Passed**MOT #8** 2016-09-09 14:06**MOT test number** 190107707503**Result** ✗ Failed

Fail Nearside Front Headlamp not working on main beam (1.7.5a)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)



MOT #7	2015-09-14 12:07
---------------	------------------

MOT test number	573036097714
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2014-09-29 09:24
---------------	------------------

MOT test number	599132874220
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2013-09-03 13:44
---------------	------------------

MOT test number	589286043230
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2012-09-07 13:57
---------------	------------------

MOT test number	825101152258
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2011-10-28 10:55
---------------	------------------

MOT test number	586251701393
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2011-03-07 15:31
---------------	------------------

MOT test number	628606961035
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2010-03-08 12:46
---------------	------------------

MOT test number	550787660013
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---

Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GJ57VMX
Plate since	2024-03-29
Current registration	 GJ57VMX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-09-28
Last registration	2021-11-24
Complete history	See info



Registration #1	2007-09-28	9 mi
Registration #2	2010-03-08	20.637 mi
Registration #3	2011-03-07	23.954 mi
Registration #4	2011-10-28	26.449 mi
Registration #5	2012-09-07	29.985 mi
Registration #6	2013-09-03	35.231 mi
Registration #7	2014-09-29	40.675 mi
Registration #8	2015-09-14	45.605 mi
Registration #9	2016-09-09	51.740 mi
Registration #10	2016-09-14	51.821 mi
Registration #11	2016-09-14	51.821 mi
Registration #12	2016-09-14	51.821 mi
Registration #13	2016-09-14	51.821 mi
Registration #14	2016-09-14	51.821 mi
Registration #15	2016-09-14	51.821 mi
Registration #16	2016-09-14	51.821 mi
Registration #17	2016-09-14	51.821 mi
Registration #18	2016-09-14	51.821 mi
Registration #19	2016-09-14	51.821 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1423 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	BMY 023990