





report date: 2024-03-28

General information

Make	JAGUAR
Model	S-TYPE V6 SE
Colour	Blue
Year of manufacture	-
Top speed	145 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	299 Nm at 4.100 rpm
Cylinders	6
Fuel type	Petrol
Consumption city	18.5 mpg
Consumption extra urban	35.3 mpg
Consumption combined	26.4 mpg



CarCheck.co.uk page 1/13




Internet history

Entry 1

Date 2021-09-05

Pictures 29

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT #20 2021-09-01 12:47

MOT test number 975616089861

Result \rightarrow Passed

Next expiry date 2022-08-31

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #19 2020-09-28 11:34

MOT test number 453626887470

Result ✓ Passed

Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Front Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #18 2019-10-14 16:05

MOT test number 215062730619

Result

Passed

MOT #17 2018-10-15 16:14

MOT test number 469974568477

Minor Nearside Rear Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Offside Rear Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

CarCheck.co.uk page 3/13



MOT #16 2017-10-10 11:58

MOT test number 943429438819

Result ✓ Passed

MOT #15 2017-10-09 12:03

MOT test number 760365895485

Result X Failed

Fail Nearside Rear Shock absorber has an excessively worn bush lower bush (2.7.4)

Fail Offside Rear Rear fog lamp not working (1.3.2b)

Advice Nearside Front Nail in tyre

MOT #14 2016-10-03 13:34

MOT test number 947369442006

Advice Nearside Rear Nail in tyre

Advice Nearside Rear Shock absorber has a slightly worn bush lower bush (2.7.4)

Advice Offside Rear Nail in tyre

MOT #13 2015-10-28 11:19

MOT test number 780867548508

Result ✓ Passed

MOT #12 2015-09-26 09:41

MOT test number 692463029892

Result ✓ Passed

CarCheck.co.uk page 4/13



Pass with rectification Offside Headlamp aim too low (1.8)

Pass with rectification Nearside Headlamp aim too low (1.8)

MOT #10

MOT test number

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

MOT #9 2014-12-05 12:41

MOT test number 228719134313

Result X Failed

Notice Engine covers fitted obscuring some components in the engine bay

Pass with rectification Offside Headlamp aim too high (1.8)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Under-trays fitted obscuring some underside components

Pass with rectification Nearside Headlamp aim too high (1.8)

Fail Offside Outer Rear Tie bar/rod ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

CarCheck.co.uk page 5/13



MOT #8 2013-11-22 11:55

MOT test number 628426823357

Notice Nearside rear tyre worn close to legal limit, persihed and cracking

Notice Nearside rear brake starting to bind

MOT #7 2012-12-01 09:57

MOT test number 398426832317

Result ✓ Passed

MOT #6 2011-11-28 09:52

MOT test number 455212231328

Result \(\sqrt{Passed} \)

MOT #5 2010-11-26 09:34

MOT test number 200260730392

Result ✓ Passed

MOT #4 2009-12-02 09:26

MOT test number 693066239341

Result ✓ Passed

MOT #3 2008-11-19 11:26

MOT test number 982604128352

Result
✓ Passed

MOT #2 2007-11-30 10:43

MOT test number 412194137334

Result

Passed

Notice O/s/f tyre wearing on inner edge and will need changing verry soon

CarCheck.co.uk page 6/13



MOT #1 2006-12-05 13:14

MOT test number 772209936320

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		ΔR

	Mana infa	
	More info	>
Plate changes		
See in this check if this JAGUAR had different number plates.		
Number of plates		9
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2003-12-05
Last registration	2021-09-01
Complete history	See info



Registration #1	2003-12-05	7 mi
Registration #2	2006-12-05	34.385 mi
Registration #3	2007-11-30	39.080 mi
Registration #4	2008-11-19	43.646 mi
Registration #5	2009-12-02	48.480 mi
Registration #6	2010-11-26	54.368 mi
Registration #7	2011-11-28	58.214 mi
Registration #8	2012-12-01	61.346 mi
Registration #9	2013-11-22	64.434 mi
Registration #10	2014-12-05	67.769 mi
Registration #11	2014-12-08	67.769 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		9.70 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es

More info >

CarCheck.co.uk page 12/13



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2040 mm
Height	1444 mm
Length	4861 mm
Wheel base	2909 mm
Kerb weight	1710 kg

Additional information

Fuel tank capacity	69 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	335539378FB

CarCheck.co.uk page 13/13