





General information

Make	JAGUAR
Model	XJ D V6 PREMIUM LUXURY
Colour	White
Year of manufacture	2013
Top speed	155 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	275 BHP
Max. torque	600 Nm at 2.000 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	43.5 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date Pictures 2021-07-03

20

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-28
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	13
Total items failed	5

MOT #9		2024-03-25 12:50
MOT test	number	386671927296
Result		Passed
Next expi	ry date	2025-03-28
Advice	Covers fitted	
Advice (i))	Subframe mounting prescribed area is corroded but not considered excess	ive both rear (5.3.6 (a)

МОТ #8	2023-03-24 16:04
MOT test number	342319756918
Result	✓ Passed

MOT #7	2022-03-25 15:21
MOT test number	649506751702
Result	✓ Passed
Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #6	2021-03-29 10:36
MOT test number	425958107058
Result	✓ Passed
Minor Offside Rear Other passenger door catch deteriorated so the door cannot be readily opened or closed (6.2.3 (c) (i))	





MOT #5	2019-06-19 14:03
MOT test number	947542077951
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MOT #4	2019-06-11 16:13
MOT test number	201448716827
Result	🗙 Failed
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its struct	ture (5.2.3 (d) (ii))
Advice Brake discs worn (all) but not considered excessive	
Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Rear Road wheel fractured (5.2.2 (a))	
Fail Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))	
Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its struct	ure (5.2.3 (d) (ii))
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3		2018-06-05 11:02
MOT test number		624915764008
Result		✓ Passed
Minor Offside Front swept area (3.2 (a) (i))	Windscreen damaged but not adver	sely affecting driver's view stone chip above





MOT #2		2017-06-02 10:35
MOT test	number	106030633039
Result		✓ Passed
Advice	Nearside Front Tyre worn smooth on edges (245/45R19)	
Advice	Offside Front tyre worn smooth on edges (245/45R19)	

MOT #1	2016-06-08 13:47
MOT test number	178772571054
Result	✓ Passed



Tax & MOT check

✓ Taxed	✓ MOT
Tax due: 1 July 2024	Expires: 28 March 2025
Tax status	Valid until 1 July
Days left	63
MOT expiry date	28 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
	E Store
Date	1. E
Category	amt
Туре	

Extra JAGUAR salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And the second sec	

	More info >
Plate changes	
See in this check if this JAGUAR had different number pla	tes.
Number of plates	7
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-03-26
Last registration	2024-03-25
Complete history	See info



Registration #1	2013-03-26	17 mi
Registration #2	2016-06-08	26.538 mi
Registration #3	2017-06-02	44.254 mi
Registration #4	2018-06-05	35.998 mi
Registration #5	2019-06-11	85.304 mi
Registration #6	2019-06-19	85.303 mi
Registration #7		11.777 est
Registration #8		11.777 est
Registration #9		11.777 est
Registration #10		11.227 est
Registration #11		11.317 est





Safety ratings

NCAP rating	****
Adult	79%
Children	73%
Pedestrian	62%
Safety systems	71%
Overall rating	74%
Video	see crash video



Dimensions & weight	
Width	1894 mm
Height	1448 mm
Length	5122 mm
Wheel base	3157 mm
Kerb weight	1796 kg
Max. allowed weight	2340 kg
Additional information	
Additional information Fuel tank capacity	82
	82 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 4