



report date: 2024-03-28

General information

Make	VAUXHALL
Model	MERIVA LIFE
Colour	Black
Year of manufacture	2017
Top speed	110 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history




Entry 3

Date	2024-02-12
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 2

Date	2024-02-03
Pictures	19
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-11-08
Pictures	5
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-09-17
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	8
Total items failed	1

MOT #5	2023-09-12 09:47
MOT test number	289683989527
Result	✓ Passed
Next expiry date	2024-09-17

MOT #4	2022-09-13 11:24
MOT test number	322620206658
Result	✓ Passed

MOT #3	2021-09-16 10:45
MOT test number	788476407212
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing tread out of shape (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing tread out of shape (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 3.0mm (5.2.3 (e))



MOT #2 2021-09-16 07:53

MOT test number 883767788426

Result ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3.0mm (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing tread out of shape (5.2.3 (d) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm 225/45R17 (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing tread out of shape (5.2.3 (d) (ii))

MOT #1 2020-09-15 09:43

MOT test number 913916333008

Result ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing tread out of shape (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing tread out of shape (5.2.3 (d) (ii))



Tax & MOT check

×

Untaxed

Tax expired:
28 January 2024

✓

MOT

Expires:
17 September 2024

Tax status	Expired at 28 January 2024
Days left	92 days too late
MOT expiry date	17 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 LX67KGZ
Plate since	2019-06-29
Current registration	 LX67KGZ
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-09-18
Last registration	2023-09-12
Complete history	See info



Registration #1	2017-09-18	22 mi
Registration #2	2020-09-15	22.328 mi
Registration #3	2021-09-16	28.665 mi
Registration #4	2021-09-16	28.665 mi
Registration #5	2023-09-12	28.665 mi
Registration #6	2023-09-12	28.665 mi
Registration #7	2023-09-12	28.665 mi
Registration #8	2023-09-12	28.665 mi
Registration #9	2023-09-12	28.665 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1376 kg
Max. allowed weight	1905 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B14XER -19PF3548LDD