





report date: 2024-03-28

General information

Make	HYUNDAI
Model	AMICA GSI
Colour	Red
Year of manufacture	2006
Top speed	91 mph
0 - 60 mph	15.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	62 BHP
Max. torque	97 Nm at 3.000 rpm
Engine capacity	1.086 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	52.3 mpg
CO2 emission	128 g/km
CO2 label	D




CarCheck.co.uk page 1/12




Internet history

Entry 1

Date	2021-09-26
Pictures	11
Listing price	<u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



✓ Passed

MOT history

Result

MOT expiry date	2024-11-14
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	7
Total items failed	3

MOT #17	2023-11-07 13:24
MOT test number	403300237941
Result	✓ Passed
Next expiry date	2024-11-14
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #16	2022-11-14 13:34
MOT test number	523924203723
Result	✓ Passed
MOT #15	2021-11-11 12:19
MOT test number	858475735233
Result	✓ Passed
MOT #14	2020-10-28 12:46
MOT test number	818460489794

MOT #13	2019-05-09 10:17
MOT test number	421091531497
Result	✓ Passed

CarCheck.co.uk page 3/12



EA06KUJ

report date: 2024-03-28

MOT #12 2018-04-30 13:46

MOT test number 966245251918

MOT #11 2017-05-03 10:07

MOT test number 699733002115

Result ✓ Passed

MOT #10 2016-04-27 10:48

MOT test number 395817271452

Result \(\sqrt{Passed} \)

MOT #9 2015-04-30 11:44

MOT test number 658620925191

Result ✓ Passed

MOT #8 2014-04-30 12:10

MOT test number 476680524161

Notice Headlamp masks/converters fitted

MOT #7 2014-04-30 12:10

MOT test number 209790224100

Result X Failed

Pass with rectification Nearside Rear Brake pipe fouled by moving parts (3.6.B.2a)

Pass with rectification Offside Rear fog lamp not working (1.3.2b)

Notice Headlamp masks/converters fitted

CarCheck.co.uk page 4/12



MOT #6

MOT test number

856591423188

Result

Notice Nail in nearside rear tyre

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT test number
765801723120

Result

Notice Nail in nearside rear tyre

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Rear Lower Stop lamp not working (1.2.1b)

MOT #4	2012-04-30 10:10
MOT test number	415211622127
Result	✓ Passed
MOT #3	2011-04-28 13:24
MOT test number	187828111106
Result	✓ Passed
MOT #2	2010-05-05 10:58
MOT test number	192475420172
Result	✓ Passed
MOT #1	2009-05-15 10:32
MOT test number	812955239161
Result	√ Passed

CarCheck.co.uk page 5/12





Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	14 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-


CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
manage of the same	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	AIR UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-04-28
Last registration	2023-11-07
Complete history	See info



Registration #1	2006-04-28	20 mi
Registration #2	2009-05-15	17.640 mi
Registration #3	2010-05-05	20.582 mi
Registration #4	2011-04-28	22.997 mi
Registration #5	2012-04-30	25.639 mi
Registration #6	2013-05-01	28.013 mi
Registration #7	2014-04-30	30.385 mi
Registration #8	2015-04-30	32.396 mi
Registration #9	2016-04-27	33.853 mi
Registration #10		77,777 44
Registration #11		71,777 66
Registration #12		71.777 es
Registration #13		71,777 66
Registration #14		71.777 es
Registration #15		71,777 66
Registration #16		D.777 es
Registration #17		11.777 ms

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1525 mm
Height	1570 mm
Length	3565 mm
Wheel base	2380 mm
Kerb weight	1007 kg
Max. allowed weight	1336 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2

Engine number G4HG6M912417