



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	EOS TDI SE
Colour	Red
Year of manufacture	2008
Top speed	127 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-03
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-11
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	44
Total items failed	6

MOT #16 2023-08-12 08:54

MOT test number 597261243720

Result ✓ Passed

Next expiry date 2024-08-11

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #15 2022-09-03 07:36

MOT test number 674129566222

Result ✓ Passed

Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #14 2021-09-04 14:48

MOT test number 536446714404

Result ✓ Passed

**MOT #13** 2020-09-11 08:31**MOT test number** 874824484528**Result** ✓ Passed**Advice** Offside Front Nail in tyre**Advice** Registration plate deteriorated but not likely to be misread front and rear (0.1 (b))**MOT #12** 2019-09-13 08:41**MOT test number** 431160487420**Result** ✓ Passed**Advice** Rear Inner Brake disc worn, pitted or scored, but not seriously weakened both rears (1.1.14 (a) (ii))**Advice** Exhaust corroded**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened both fronts (1.1.14 (a) (ii))**Advice** Registration plate deteriorated but not likely to be misread both plates (0.1 (b))**MOT #11** 2018-09-13 13:53**MOT test number** 806612264708**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Exhaust System Corroded

**MOT #10** 2018-09-13 13:53**MOT test number** 251622543622**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**Advice** Exhaust System Corroded**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #9** 2017-06-22 14:16**MOT test number** 236679920059**Result** ✓ Passed**Advice** Nearside Rear tyre worn to limit on inner edge**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear floor undertray damaged**Advice** Offside Rear tyre wearing uneven on inner edge**MOT #8** 2016-06-17 07:57**MOT test number** 857513205329**Result** ✓ Passed**Advice** Exhaust corroding**Advice** Engine covers and undertrays fitted

**MOT #7**

2015-05-30 12:17

MOT test number

667440555109

Result

✓ Passed

- Advice** Front Road wheel slightly damaged (4.2.A.1a)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Rear Shock absorber has a light misting of oil (2.7.3)
- Notice** Engine covers fitted obscuring some components in the engine bay

MOT #6

2015-05-30 10:56

MOT test number

355680455144

Result

✗ Failed

- Advice** Front Road wheel slightly damaged (4.2.A.1a)
- Fail** Nearside Headlamp aim too low (1.8)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Rear Shock absorber has a light misting of oil (2.7.3)
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
- Notice** Engine covers fitted obscuring some components in the engine bay

MOT #5

2014-05-28 12:24

MOT test number

206538744450

Result

✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Exhaust corroding
- Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #4** 2013-05-31 09:04**MOT test number** 589581753144**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Both front tyres worn very low on inner edges**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2012-03-05 10:10**MOT test number** 318415362070**Result** ✓ Passed**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #2** 2012-03-05 10:10**MOT test number** 777315762018**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #1** 2011-03-08 15:46**MOT test number** 266357361085**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
11 August 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	11 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 YE08TDV
Plate since	2019-03-29
Current registration	 YE08TDV
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In kilometers
Mileage registrations	17
First mileage registration	2008-05-15
Last registration	2023-08-12
Complete history	See info



Registration #1	2008-05-15	23 mi
Registration #2	2011-03-08	46.044 mi
Registration #3	2012-03-05	61.984 mi
Registration #4	2013-05-31	73.668 mi
Registration #5	2014-05-28	88.425 mi
Registration #6	2015-05-30	104.621 mi
Registration #7	2015-05-30	104.621 mi
Registration #8	2016-06-17	125.153 mi
Registration #9	2017-06-22	143.464 mi
Registration #10	2018-06-22	161.775 mi
Registration #11	2019-06-22	180.086 mi
Registration #12	2020-06-22	198.397 mi
Registration #13	2021-06-22	216.708 mi
Registration #14	2022-06-22	235.019 mi
Registration #15	2023-06-22	253.330 mi
Registration #16	2024-06-22	271.641 mi
Registration #17	2025-06-22	289.952 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1715 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BKP 293807