



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CC TDI BLUEMOTION TECHNOLOGY DSG
Colour	Silver
Year of manufacture	2012
Top speed	132 mph
0 - 100 km/h	9.8 seconds
0 - 60 mph	9.8 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	60.1 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-08-02
Pictures	23
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-16
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	22
Total items failed	5

MOT #16	2023-08-17 12:54
MOT test number	446503132022
Result	✓ Passed
Next expiry date	2024-08-16
Advice	Engine covers fitted obscuring some components
Advice	No smoke detected Diesel Particulate Filter fitted. No print out produced Engine does not rev
Advice	Undertrays fitted obscuring some components

MOT #15	2022-04-27 11:28
MOT test number	674160583299
Result	✓ Passed
Advice	Rear Child Seat fitted not allowing full inspection of adult belt

MOT #14	2021-05-08 12:36
MOT test number	561120660072
Result	✓ Passed

**MOT #13** 2020-05-23 14:37**MOT test number** 685223139265**Result** ✓ Passed

- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12 2020-05-23 11:58**MOT test number** 388047898285**Result** ✗ Failed

- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11 2019-05-13 11:41**MOT test number** 327137656619**Result** ✓ Passed**MOT #10** 2018-11-22 15:20**MOT test number** 680619577926**Result** ✓ Passed

**MOT #9** 2018-11-07 16:35**MOT test number** 316890456679**Result** ✓ Passed**MOT #8** 2018-11-07 15:01**MOT test number** 206048619493**Result** ✗ Failed**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #7** 2018-05-07 10:18**MOT test number** 549430073140**Result** ✓ Passed**MOT #6** 2017-11-07 13:51**MOT test number** 343914506205**Result** ✓ Passed**MOT #5** 2017-05-16 14:28**MOT test number** 523449253067**Result** ✓ Passed**MOT #4** 2016-11-18 15:14**MOT test number** 831490782440**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #3** 2016-08-12 10:20**MOT test number** 233573989584**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**MOT #2** 2016-08-11 14:56**MOT test number** 154443224434**Result** ✗ Failed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2015-06-17 09:48**MOT test number** 919638765132**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
16 August 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	16 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	FR12NXO
Plate since	2024-03-28
Current registration	FR12NXO
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-07-06
Last registration	2023-08-17
Complete history	See info



Registration #1	2012-07-06	15 mi
Registration #2	2015-06-17	61.957 mi
Registration #3	2016-08-11	81.655 mi
Registration #4	2016-08-12	81.662 mi
Registration #5	2016-11-18	81.934 mi
Registration #6	2017-05-16	89.007 mi
Registration #7	2017-11-07	97.837 mi
Registration #8	2018-05-07	108.825 mi
Registration #9	2018-11-07	116.613 mi
Registration #10	2019-05-20	121.277 mi
Registration #11	2019-05-20	121.277 mi
Registration #12	2019-05-20	121.277 mi
Registration #13	2019-05-20	121.277 mi
Registration #14	2019-05-20	121.277 mi
Registration #15	2019-05-20	121.277 mi
Registration #16	2019-05-20	121.277 mi
Registration #17	2019-05-20	121.277 mi
Registration #18	2019-05-20	121.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	2090 mm
Height	1421 mm
Length	4902 mm
Wheel base	2710 mm
Kerb weight	1564 kg
Max. allowed weight	2070 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CFFB817289