

Ford



General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Grey
Year of manufacture	2012
Top speed	120 mph
0 - 100 km/h	11.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	103 kW / 140 HP / 161 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G







Internet history

Entry 1

Date Pictures 2021-08-17

Listing price

View report

27



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-21
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	32
Total items failed	5

MOT #12	2023-12-20 15:28
MOT test number	423526758615
Result	✓ Passed
Next expiry date	2024-12-21

MOT #11	2022-12-22 12:24
MOT test number	285891830747
Result	✓ Passed
Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excess (a) (i))	sive movement (5.3.4
Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, b ingress of dirt (2.1.3 (g) (i))	out preventing the
Advice Rear Suspension arm corroded but not seriously weakened bothsides (5.3.	3 (b) (i))
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	



MJ62XYC	
report date: 2024-03-29)

MOT #10	2022-12-22 10:04
MOT test number	797044746107
Result	🗙 Failed
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Rear Suspension arm corroded but not seriously weakened bothsides (5.3.	3 (b) (i))
Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, b ingress of dirt (2.1.3 (g) (i))	out preventing the
Fail Nearside Rear Position lamp not working (4.2.1 (a) (ii))	
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excess (a) (i))	sive movement (5.3.4

MOT #9	2021-08-26 14:39
MOT test number	199910877230
Result	🗸 Passed
Advice Offside Rear Suspension arm pin or bush worn but not resulting in arm bush (5.3.4 (a) (i))	n excessive movement trailing

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

MOT #8		2020-10-05 13:56
MOT test	number	283446536797
Result		✓ Passed
Advice	Rear Coil spring corroded both sides (5.3.1 (b) (i))	
Advice	Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))	
Advice (a) (i))	Rear Suspension arm pin or bush worn but not resulting in excessive movemer	nt both sides (5.3.4
Advice	Under vehicle prescribed area and suspension/braking/exhaust components sli	ightly corroded
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both sides	(1.1.14 (a) (ii))
Advice	Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))	





MOT #7	2	2019-09-09 12:33
MOT test	number	519494834915
Result		🗸 Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	High level brake light inoperative	
Advice	Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened	l (1.1.14 (a) (ii))

MOT #6	2018-10-25 1	3:50
MOT test	number 984223957	/210
Result	✓ Pa:	ssed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Rear Child Seat fitted not allowing full inspection of adult belt x3	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	





MOT #5		2018-10-24 14:24
MOT test	number	849925398771
Result		🗙 Failed
Advice (e))	Nearside Rear Tyre worn close to legal limit/worn on edge 225/50/17 cracked a	nd perished (5.2.3
Fail O	ffside Front Tyre tread depth below requirements of 1.6mm 225/50/17 (5.2.3 (e)))
Advice	Rear Child Seat fitted not allowing full inspection of adult belt x3	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.3	1.14 (a) (ii))
Advice (e))	Offside Rear Tyre worn close to legal limit/worn on edge 225/50/17 cracked and	d perished (5.2.3
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 225/50/17 (5.2.3 (e))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (2	1.1.14 (a) (ii))

МОТ #4	2017-10-20 09:13
MOT test number	154284571009
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #3	2016-10-12 15:00
MOT test number	166579531199

MOT test number	166579531199
Result	✓ Passed

MOT #2	2015-09-24 14:21
MOT test number	752301500764
Result	✓ Passed





MOT #1	2015-09-24 10:59
MOT test number	656283397443
Result	🗙 Failed
Fail Nearside Front Tyre has a cut in excess of the requirements deep enoug (4.1.D.1a)	h to reach the ply or cords



Tax & MOT check

Taxed Tax due: 1 February 2025	✓ MOT Expires: 21 December 2024
Tax status	Valid until 1 February
Days left	277
MOT expiry date	21 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Residues of states	
anner o para	,
Current registration	
Carrent registration Plate since	
Carrent registration Farte since Carrent registration	
Carrent registration Fals since Fals since	8775-25-27





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-11-26
Last registration	2023-12-20
Complete history	See info



Registration #1	2012-11-26	25 mi
Registration #2	2015-09-24	18.901 mi
Registration #3	2015-09-24	18.901 mi
Registration #4	2016-10-12	21.328 mi
Registration #5	2017-10-20	25.543 mi
Registration #6	2018-10-24	30.780 mi
Registration #7	2018-10-25	30.780 mi
Registration #8		10.317 mil
Registration #8 Registration #9		11.777 es
-		11,117 es
Registration #9		01,000 est 01,000 est 01,000 est 01,000 est
Registration #9 Registration #10		01,000 46 01,000 46 01,000 46 01,000 46 01,000 46
Registration #9 Registration #10 Registration #11		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1688 kg
Max. allowed weight	2505 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 14/14

Number of axles	2
Engine number	CY74072