



report date: 2024-03-28

General information

Make	FIAT
Model	DOBLO 16V MULTIJET
Colour	White
Year of manufacture	2011
Top speed	97 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2024-09-13
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	21
Total items failed	5

MOT #10	2020-07-07 15:00
MOT test number	731166699934
Result	✓ Passed
Next expiry date	2021-07-06
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2019-07-01 14:19
MOT test number	235381084420
Result	✓ Passed
Advice	Power steering component has slight seepage from a component rack (2.1.5 (a))
Advice	Exhaust heat shield loose

MOT #8	2019-07-01 10:12
MOT test number	652457479470
Result	✗ Failed
MAJOR	Spare wheel insecure in carrier (6.1.5 (b) (i))
Advice	Power steering component has slight seepage from a component rack (2.1.5 (a))
Advice	Exhaust heat shield loose

**MOT #7** 2018-06-29 13:05**MOT test number** 354496965137**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2018-06-28 09:21**MOT test number** 959918652088**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Heat shield insecure**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #5** 2017-07-11 11:14**MOT test number** 825024565708**Result** ✓ Passed**MOT #4** 2016-07-01 15:58**MOT test number** 305777569928**Result** ✓ Passed**MOT #3** 2015-06-24 15:10**MOT test number** 318135175116**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)**Notice** Brake pedal rubber missing**Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)

**MOT #2**

2015-06-24 10:07

MOT test number

579055675171

Result**✗ Failed**

- Fail** Front brake application uneven (3.7.B.2)
- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)
- Notice** Front brake discs corroded and wearing thin
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)
- Fail** Front Brakes imbalanced across an axle (3.7.B.5b)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Notice** Brake pedal rubber missing
- Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #1

2014-06-26 10:24

MOT test number

896407374110

Result**✓ Passed**

- Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed

Tax due:
1 October 2024

✓
MOT

Expires:
13 September 2024

Tax status		Valid until 1 October
Days left		154
MOT expiry date		13 September 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2011-06-29
Last registration	2020-07-07
Complete history	See info



Registration #1	2011-06-29	17 mi
Registration #2	2014-06-26	38.732 mi
Registration #3	2015-06-24	50.339 mi
Registration #4	2015-06-24	50.339 mi
Registration #5	2016-07-01	60.825 mi
Registration #6	2017-07-11	71.295 mi
Registration #7	2019-06-29	75.277 mi
Registration #8	2019-06-29	75.277 mi
Registration #9	2019-06-29	75.277 mi
Registration #10	2019-06-29	75.277 mi
Registration #11	2019-06-29	75.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	4259452