



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SE 5STR
Colour	Silver
Year of manufacture	2008
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	156 g/km
CO2 label	G





## MOT history

MOT expiry date	2024-10-31
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	22
Total items failed	7

MOT #17	2023-10-28 11:14
MOT test number	847606805163
Result	✓ Passed
Next expiry date	2024-10-31
Advice	Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #16	2022-11-01 14:58
MOT test number	932729131164
Result	✓ Passed
Advice	Front Play in steering rack inner joint(s) Nearside and Offside
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #15	2022-10-27 16:06
MOT test number	145112296858
Result	✗ Failed
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Fail	Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Front Play in steering rack inner joint(s) Nearside and Offside

**MOT #14**

2021-10-23 11:13

**MOT test number**

570913893380

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge Tyre worn out on inner edge / Tyre size 205/55R16 (5.2.3 (e))

**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated Drop link cover split (5.3.4 (b) (i))

**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated Cover deteriorated / split (5.3.4 (b) (i))

**MOT #13**

2021-10-23 09:00

**MOT test number**

775998401747

**Result**

✗ Failed

**Fail** Nearside Front Tyre has ply or cords exposed Damage to outer tyre wall / Tyre size 205/55R16 (5.2.3 (d) (ii))

**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated Drop link cover split (5.3.4 (b) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge Tyre worn out on inner edge / Tyre size 205/55R16 (5.2.3 (e))

**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated Cover deteriorated / split (5.3.4 (b) (i))

**MOT #12**

2020-10-12 09:33

**MOT test number**

273212651313

**Result**

✓ Passed

**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #11**

2019-10-17 10:17

**MOT test number**

972608349947

**Result**

✓ Passed

**MOT #10**

2018-10-25 14:52

**MOT test number**

761791616819

**Result**

✓ Passed

**Advice**

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #9** 2018-10-25 10:08**MOT test number** 116823386129**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Exhaust emissions test aborted because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))**MOT #8** 2017-10-25 13:04**MOT test number** 856190129968**Result** ✓ Passed**MOT #7** 2016-10-28 13:56**MOT test number** 829759013020**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**MOT #6** 2016-10-24 13:31**MOT test number** 130925541125**Result** ✗ Failed**Fail** Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)**Advice** Nearside Rear Nail in tyre**MOT #5** 2015-10-29 14:03**MOT test number** 644119129090**Result** ✓ Passed**Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #4** 2014-06-27 12:41**MOT test number** 808848274148**Result** ✓ Passed**Notice** Child seat fitted to nearside rear seat.**Notice** Front wiper blades starting to smear**Notice** Luggage in boot, unable to check 3rd row seats and seat belts.**MOT #3** 2013-06-27 14:33**MOT test number** 229748173180**Result** ✓ Passed**MOT #2** 2012-06-29 11:00**MOT test number** 685961282168**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2011-04-09 11:14**MOT test number** 479429091096**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
31 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	31 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>OV08GNF</b>
Plate since	2024-03-28
Current registration	 <b>OV08GNF</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-04-10
Last registration	2023-10-28
Complete history	<a href="#">See info</a>



Registration #1	2008-04-10	13 mi
Registration #2	2011-04-09	27.392 mi
Registration #3	2012-06-29	37.332 mi
Registration #4	2013-06-27	44.149 mi
Registration #5	2014-06-27	52.395 mi
Registration #6	2015-10-29	63.170 mi
Registration #7	2016-10-24	72.358 mi
Registration #8	2016-10-28	72.461 mi
Registration #9	2017-10-25	81.823 mi
Registration #10	2018-10-25	91.185 mi
Registration #11	2019-10-25	100.547 mi
Registration #12	2020-10-25	109.909 mi
Registration #13	2021-10-25	119.271 mi
Registration #14	2022-10-25	128.633 mi
Registration #15	2023-10-25	137.995 mi
Registration #16	2024-10-25	147.357 mi
Registration #17	2025-10-25	156.719 mi
Registration #18	2026-10-25	166.081 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BXE A27658