



HONDA



report date: 2024-03-28

General information

Make	HONDA
Model	CR-V I-DTEC EX
Colour	Black
Year of manufacture	2018
Top speed	123 mph
0 - 60 mph	10.4 seconds
Gearbox	9 speed automatic

Engine & fuel consumption

Power	158 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	1.597 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	57.6 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 3

Date	2021-07-27
Pictures	22
Listing price	View report



source: yesauto.com

Entry 2


Date	2021-07-22
Pictures	22
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-21
Pictures	22
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-26
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	11
Total items failed	3

MOT #5	2023-06-22 09:34
MOT test number	779476531074
Result	✓ Passed
Next expiry date	2024-06-26
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #4	2022-06-10 12:34
MOT test number	358864681142
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))

MOT #3	2022-06-08 14:40
MOT test number	632254095426
Result	✗ Failed
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))
Fail	Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Minor	Offside Windscreen wiper blade defective (3.4 (b) (i))
Advice	Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))

**MOT #2**

2021-06-23 14:32

MOT test number

390566274738

Result

✓ Passed

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice

Rear Passenger seat(s) missing at time of test All rear seats missing and car full

MOT #1

2021-06-23 13:23

MOT test number

213018770953

Result

✗ Failed

Fail

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice

Rear Passenger seat(s) missing at time of test All rear seats missing and car full

Fail

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Front Brake disc worn, but not excessively (1.1.14 (a) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
26 June 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	26 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-06-27
Last registration	2023-06-22
Complete history	See info



Registration #1	2018-06-27	29 mi
Registration #2	2021-06-23	25.639 mi
Registration #3	2021-06-23	25.640 mi
Registration #4	2022-06-22	25.639 mi
Registration #5	2022-06-22	25.639 mi
Registration #6	2022-06-22	25.639 mi
Registration #7	2022-06-22	25.639 mi
Registration #8	2022-06-22	25.639 mi
Registration #9	2023-06-22	25.640 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	74%
Pedestrian	68%
Safety systems	66%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2095 mm
Height	1685 mm
Length	4605 mm
Wheel base	2630 mm
Kerb weight	1724 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	N16A42205075