



report date: 2024-03-29

General information

Make	SUZUKI
Model	SWIFT SZ4 DDIS
Colour	Silver
Year of manufacture	2014
Top speed	103 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	101 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-04-25
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	19
Total items failed	5

MOT #10	2024-04-09 15:33
MOT test number	704826100691
Result	✓ Passed
Next expiry date	2025-04-25
Advice	Rear shock absorbers corroded

MOT #9	2023-04-03 16:09
MOT test number	125392318208
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	All wipers need replaced
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement Starting to perish (5.3.4 (a) (i))
Advice	Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2023-04-03 09:56**MOT test number** 711743432550**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Front Tyre tread depth below requirements of 1.6mm Both (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** All wipers need replaced**Advice** Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement Starting to perish (5.3.4 (a) (i))**MOT #7** 2022-04-22 13:25**MOT test number** 969465466638**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #6** 2022-04-22 09:53**MOT test number** 899466849474**Result** ✗ Failed**Fail** Front Tyre tread depth below requirements of 1.6mm Both (5.2.3 (e))**MOT #5** 2021-04-26 09:00**MOT test number** 138125013617**Result** ✓ Passed

**MOT #4** 2019-10-01 15:11**MOT test number** 188960848990**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2019-09-27 09:12**MOT test number** 132894320145**Result** ✗ Failed**Fail** Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #2** 2018-10-01 11:39**MOT test number** 592088318507**Result** ✓ Passed**MOT #1** 2017-09-22 14:02**MOT test number** 548802939202**Result** ✓ Passed**Advice** Too much reverse travel on handbrake



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
25 April 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	25 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	KN64OSR
Plate since	2019-09-29
Current registration	KN64OSR
Plate since	2019-09-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-10-01
Last registration	2024-04-09
Complete history	See info



Registration #1	2014-10-01	26 mi
Registration #2	2017-09-22	20.498 mi
Registration #3	2018-10-01	23.490 mi
Registration #4	2019-09-27	29.509 mi
Registration #5	2019-10-01	29.524 mi
Registration #6	2019-10-01	29.524 mi
Registration #7	2019-10-01	29.524 mi
Registration #8	2019-10-01	29.524 mi
Registration #9	2019-10-01	29.524 mi
Registration #10	2019-10-01	29.524 mi
Registration #11	2019-10-01	29.524 mi
Registration #12	2019-10-01	29.524 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	1140 kg
Max. allowed weight	1560 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	D13AA5106981