



report date: 2024-03-29

## General information

Make	VOLVO
Model	C70 D5 SPORT
Colour	Black
Year of manufacture	2008
Top speed	140 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	178 BHP
Max. torque	400 Nm at 2.750 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg
CO2 emission	174 g/km
CO2 label	H





## MOT history

MOT expiry date	2021-07-29
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	23
Total items failed	21

## MOT #14 2020-07-18 12:13

MOT test number 155131529354

Result ✓ Passed

Next expiry date 2021-07-29

**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement outer bush (5.3.4 (a) (i))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement outer bush (5.3.4 (a) (i))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

## MOT #13 2019-07-30 15:20

MOT test number 602884384797

Result ✓ Passed

## MOT #12 2019-06-21 09:43

MOT test number 376640043807

Result ✗ Failed

**Fail** Suspension arm pin or bush excessively worn both front lower arm bushes worn (5.3.4 (a) (i))

**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Advice** Advise rear tyres inside edges

**MOT #11** 2018-05-29 12:48**MOT test number** 797142445841**Result** ✓ Passed**MOT #10** 2018-05-23 14:22**MOT test number** 450651291997**Result** ✗ Failed

- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Rear Seat belt buckle not functioning as intended (7.1.2 (d))
- Fail** Additional braking device connector insecure and functionality of device affected ABS unit insecure (1.1.19 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))
- Fail** Battery insecure and likely to cause a short circuit (4.13 (a) (ii))
- Fail** Anti-lock braking system warning lamp does not illuminate (1.6 (a))
- Fail** Brake lever has insufficient reserve travel (1.1.2 (a))
- Fail** Nearside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))

**MOT #9** 2016-11-22 17:09**MOT test number** 884782827879**Result** ✓ Passed

- Advice** Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**MOT #8** 2015-11-20 13:12**MOT test number** 642564696455**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front wipers smear**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2014-11-19 17:21**MOT test number** 725793224320**Result** ✓ Passed**Advice** Offside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**MOT #6** 2013-11-21 17:00**MOT test number** 277575923380**Result** ✓ Passed**Advice** Offside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2013-11-19 14:36**MOT test number** 147243923366**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-09-06 14:53**MOT test number** 996970652258**Result** ✓ Passed**MOT #3** 2012-09-06 09:31**MOT test number** 566680352281**Result** ✗ Failed**Fail** Nearside Rear Anti-roll bar has excessive play in a pin/bush (2.4.G.2)**Fail** Offside Stop lamp not working (1.2.1b)**MOT #2** 2011-09-14 16:14**MOT test number** 376797951275**Result** ✓ Passed



MOT #12011-09-14 12:10

MOT test number735807151216

Result

Failed

AdviceOffside Rear Tyre worn close to the legal limit (4.1.E.1)

FailOffside Front Tyre has ply or cords exposed (4.1.D.1b)

FailOffside Headlamp aim too low (1.8)

FailNearside Front Tyre has ply or cords exposed (4.1.D.1b)

FailNearside Stop lamp not working (1.2.1b)



Tax & MOT check

✕  
Untaxed

Tax expired:  
31 January 2021

✕  
MOT

Expired:  
29 July 2021

Tax status	Expired at 31 January 2021
Days left	1185 days too late
MOT expiry date	29 July 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-07-08
Last registration	2020-07-18
Complete history	<a href="#">See info</a>



Registration #1	2008-07-08	15 mi
Registration #2	2011-09-14	37.009 mi
Registration #3	2011-09-14	37.009 mi
Registration #4	2012-09-06	57.602 mi
Registration #5	2012-09-06	57.602 mi
Registration #6	2013-11-19	74.682 mi
Registration #7	2013-11-21	74.698 mi
Registration #8	2014-11-19	86.801 mi
Registration #9	2015-05-20	86.801 mi
Registration #10	2015-05-20	86.801 mi
Registration #11	2015-05-20	86.801 mi
Registration #12	2015-05-20	86.801 mi
Registration #13	2015-05-20	86.801 mi
Registration #14	2015-05-20	86.801 mi
Registration #15	2015-05-20	86.801 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1847 mm
Height	1400 mm
Length	4582 mm
Wheel base	2640 mm
Kerb weight	1772 kg
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

**Engine number**

626544