






General information

Make	JAGUAR
Model	X-TYPE V6 SPORT
Colour	Grey
Year of manufacture	2007
Top speed	137 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	244 Nm at 3.000 rpm
Engine capacity	2.496 cc
Cylinders	6
Fuel type	Petrol
Consumption city	19.0 mpg
Consumption extra urban	37.2 mpg
Consumption combined	27.4 mpg
CO2 emission	244 g/km
CO2 label	L





Internet history		
Entry 1		
Date	2022-01-17	
Pictures	5	
Listing price	View report	
Free Cet Covered Today Covered Today <	<section-header></section-header>	AutoTrader Reviews Read our 5 star reviews



MOT history

MOT expiry date	2025-02-23
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	50
Total items failed	4

MOT #18	2024-01-26 17:18
MOT test number	940999495341
Result	🗸 Passed
Next expiry date	2025-02-23
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Vehicle structure & suspension related components Coated In Underseal	
Advice Outer Sill cover/trims fitted unable to carry out inspection On Sill	

MOT #17

MOT test number

Result	✓ Passed	
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Unable to inspect outer sills due to covers	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Surface rust both rear inner sills	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))	
Advice	Underside of vehicle undearsealed	

2023-02-03 13:37 419521812052





MOT #16		2023-02-03 09:27
MOT test i	number	788268869723
Result		🗙 Failed
MAJOR	Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.	2.1.2 (b))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Underside of vehicle undearsealed	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Unable to inspect outer sills due to covers	
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Advice	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement bo	oth (5.3.4 (a) (i))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Surface rust both rear inner sills	

MOT #15	2022-02-24 15:33
MOT test number	325802994749
Result	✓ Passed



DE07GFU
report date: 2024-03-29

MOT #14		2022-02-15 12:47
MOT test	number	173394318504
Result		🗙 Failed
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
MAJOR	Nearside Front Seat belt damaged (7.1.2 (b) (i))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)) (ii))
MAJOR reducing s	Offside Rear Suspension component mounting prescribed area excessively co tructural strength (5.3.6 (a) (i))	rroded significantly
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
MAJOR	Emissions not tested (8.2.1.2 (d))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR significant	Nearside Rear Suspension component mounting prescribed area excessively only reducing structural strength (5.3.6 (a) (i))	corroded
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #13		2021-04-30 14:48
MOT test	number	567289695681
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge on the edges (5.2.3 (e)))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Nearside Front Seat belt slightly damaged (7.1.2 (b) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	



MOT #12	20	021-04-30 14:48
MOT test	number	883572466214
Result		🗙 Failed
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	ce Nearside Front Seat belt slightly damaged (7.1.2 (b) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge on the edges (5.2.3 (e))		
Advice Oil leak, but not excessive (8.4.1 (a) (i))		
Pass with rectification Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))		

MOT #11		2018-06-27 11:08
MOT test numbe	r	483277039805
Result		🗙 Failed
DANGEROUS	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
MAJOR Exhau	ust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c	2))
DANGEROUS	Rear Brake pad(s) less than 1.5 mm thick ($1.1.13$ (a) (ii))	
MAJOR Headl	amp aim not tested (4.1.2 (b))	
MAJOR Engine	e MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Advice Front	Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a	a) (ii))
MAJOR Nears	ide Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #10		2017-06-14 09:06
MOT test	number	420896757684
Result		✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	



DE07GFU
report date: 2024-03-29

MOT #9	2017-06-14 09:06	
MOT test number	364443481977	
Result	🗙 Failed	
Advice Rear Brake pad(s) wearing thin (3.5.1g)		
Pass with rectification Nearside Headlamp not working on dipped beam (1.7.5a)		
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)		
Advice Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)		
Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)		

МОТ #8	2016-05-23 09:29
MOT test number	388923711853
Result	✓ Passed

MOT #7	2016-05-17 08:23
MOT test number	558482545817
Result	🗙 Failed
Fail Shock absorber has an excessively worn bush both rear (2.7.4)	

MOT #6	2015-06-10 17:05
MOT test number	527561865108
Result	✓ Passed
MOT #5	2014-07-30 10:47
MOT test number	437731214224
Result	✓ Passed

MOT #4	2013-07-31 11:41
MOT test number	207872113265
Result	✓ Passed





MOT #3	2012-07-19 13:09
MOT test number	907411102247
Result	✓ Passed
MOT #2	2011-07-29 15:13
MOT test number	306930111288
Result	✓ Passed
MOT #1	2010-07-19 10:20
MOT test number	911910500286
Result	✓ Passed



Tax & MOT check

X Untaxed Tax expired: 18 April 2024	✓ MOT Expires: 23 February 2025
Tax status	Expired at 18 April 2024
Days left	12 days too late
MOT expiry date	23 February 2025
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-





Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damaye 2	6 - 6t - D - D
Date	1. Sterrer and a start of the s
Category	AMP
Туре	

Extra JAGUAR salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And the second sec	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plate	25.
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-03-29
Last registration	2024-01-26
Complete history	See info



Registration #1	2007-03-29	26 mi
Registration #2	2010-07-19	23.135 mi
Registration #3	2011-07-29	26.002 mi
Registration #4	2012-07-19	28.296 mi
Registration #5	2013-07-31	31.397 mi
Registration #6	2014-07-30	35.335 mi
Registration #7	2015-06-10	39.137 mi
Registration #8	2016-05-17	48.713 mi
Registration #9	2016-05-23	48.715 mi
Registration #10	2017-06-14	70.259 mi
Registration #11		11.777 est
Registration #12		11.777 est
Registration #13		11.777 est
Registration #14		11.777 est
Registration #15		11.777 est
Registration #16		11.777 est
Registration #17		11.777 est
Registration #18		11.777 est
Registration #19		11.777 mi
Registration #20		11.117 est







Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1595 kg
Max. allowed weight	2080 kg
Additional information	
Additional information Fuel tank capacity	61 I
	61 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 4