




report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | VOLKSWAGEN |
| Model | TOURAN S TDI |
| Colour | Black |
| Year of manufacture | 2011 |
| Top speed | 114 mph |
| 0 - 100 km/h | 12.8 seconds |
| 0 - 60 mph | 12.8 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|--------------------------|
| Power | 77 kW / 105 HP / 106 BHP |
| Max. torque | 250 Nm at 1.500 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 44.8 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 6.3 mpg |
| CO2 emission | 134 g/km |
| CO2 label | E |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-12-18 |
| Pictures | 12 |
| Listing price | View report |



source: cargurus.co.uk

**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2024-11-22 |
| MOT pass rate | 77 % |
| MOT passed | 10 |
| Failed MOT tests | 3 |
| Total advice items | 25 |
| Total items failed | 3 |

MOT #13 2023-11-20 19:36**MOT test number** 570386812280**Result** Passed**Next expiry date** 2024-11-22

- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Shock absorbers has light misting of oil Both sides (5.3.2 (b))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement Both sides rear bushes (5.3.4 (a) (i))
- Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #12 2022-11-23 14:28**MOT test number** 726835443516**Result** Passed

- Advice** Front Shock absorbers has light misting of oil Both sides (5.3.2 (b))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement Both sides rear bush (5.3.4 (a) (i))
- Advice** Rear Anti-roll bar linkage ball joint has slight play Both sides (5.3.4 (a) (i))

MOT #11 2021-08-05 11:26**MOT test number** 300118668315**Result** Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))

**MOT #10** 2020-07-29 16:38**MOT test number** 931971931403**Result** ✓ Passed**MOT #9** 2019-07-31 10:46**MOT test number** 145328066887**Result** ✓ Passed**MOT #8** 2018-08-09 09:05**MOT test number** 183394241764**Result** ✓ Passed**MOT #7** 2018-08-07 11:20**MOT test number** 976025855690**Result** ✗ Failed

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #6 2017-03-01 09:42**MOT test number** 917939096111**Result** ✓ Passed

Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #5 2017-03-01 09:20**MOT test number** 916664842783**Result** ✗ Failed

Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #4**

2016-02-25 08:06

MOT test number

595256590134

Result

✓ Passed

- Advice** O/s/f tyre bald inner edge, side wall worn
- Advice** Nearside Rear Tyre worn close to the legal limit side wall worn, bald outer edge and cracking (4.1.E.1)
- Advice** O/s/r tyre side wall worn and cracking
- Advice** N/s/f tyre side wall worn, cut in side wall
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

MOT #3

2016-02-15 09:19

MOT test number

896892855091

Result

✗ Failed

- Advice** N/s/f tyre side wall worn, cut in side wall
- Advice** Nearside Rear Tyre worn close to the legal limit side wall worn, bald outer edge and cracking (4.1.E.1)
- Advice** O/s/f tyre bald inner edge, side wall worn
- Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)
- Advice** O/s/r tyre side wall worn and cracking
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

MOT #2

2015-02-13 09:13

MOT test number

478424945050

Result

✓ Passed

- Notice** Both rear tyres cracking
- Notice** Small cut in n/s/r tyre side wall
- Notice** Both rear tyre side walls worn



| | |
|-----------------|------------------|
| MOT #1 | 2014-03-07 15:55 |
| MOT test number | 899556664073 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
22 November 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 January |
| Days left | 247 |
| MOT expiry date | 22 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | FY11RJU |
| Plate since | 2019-03-29 |
| Current registration | FY11RJU |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


| | | |
|-------------------|------------|--------|
| Finance company | XXXXXXXXXX | XXXXXX |
| Date of agreement | XXXXXXXXXX | XXXXXX |
| Agreement type | XXXXXXXXXX | XXXXXX |
| Agreement term | XXXXXXXXXX | XXXXXX |
| Agreement number | XXXXXXXXXX | XXXXXX |
| Contact info | XXXXXXXXXX | XXXXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 15 |
| First mileage registration | 2011-03-10 |
| Last registration | 2023-11-20 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2011-03-10 | 24 mi |
| Registration #2 | 2014-03-07 | 58.214 mi |
| Registration #3 | 2015-02-13 | 41.338 mi |
| Registration #4 | 2016-02-15 | 51.473 mi |
| Registration #5 | 2016-02-25 | 51.473 mi |
| Registration #6 | 2017-03-01 | 62.098 mi |
| Registration #7 | 2017-03-01 | 62.098 mi |
| Registration #8 | 2018-08-07 | 72.118 mi |
| Registration #9 | 2019-05-20 | 75.277 mi |
| Registration #10 | 2019-05-20 | 75.277 mi |
| Registration #11 | 2019-05-20 | 75.277 mi |
| Registration #12 | 2019-05-20 | 75.277 mi |
| Registration #13 | 2019-05-20 | 75.277 mi |
| Registration #14 | 2019-05-20 | 75.277 mi |
| Registration #15 | 2019-05-20 | 75.277 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|-------------|---------|
| Width | 1794 mm |
| Height | 1634 mm |
| Length | 4397 mm |
| Wheel base | 2678 mm |
| Kerb weight | 1539 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |

Number of axles

2

Engine number

CAY 586764