



report date: 2024-03-29

General information

Make	CITROEN
Model	C4 GRAND PICASSO GRAND BLUEHDI FEEL S/S
Colour	Black
Year of manufacture	2017
Top speed	117 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	74.3 mpg
Consumption combined	70.6 mpg
CO2 emission	106 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-10-17
MOT pass rate	100 %
MOT passed	4
Failed MOT tests	0
Total advice items	24
Total items failed	0

MOT #42023-10-05 13:32

MOT test number709447764479

Result✓ Passed

Next expiry date2024-10-17

- Advice** Nearside Front Outer Tyre slightly damaged side wall (5.2.3 (d) (ii))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front slight knocking from steering
- Advice** Nearside Rear Outer Tyre slightly damaged side wall (5.2.3 (d) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement back bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge tyre tread on 3mm. (5.2.3 (e))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged tread on 3mm on outer edge (5.2.3 (d) (ii))
- Advice** Front Coolant leak coolant leak from thermostat housing
- Advice** Nearside Rear Exhaust mounting defective exhaust rear silencer mounting rubber bonding worn (6.1.2 (a))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement back bush (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge tread on 3mm (205 55 R17 95V)tyre wearing low on inner edge (5.2.3 (e))
- Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #3**

2022-10-18 09:03

MOT test number

654605091262

Result

✓ Passed

- Advice** Nearside Front Coolant leak thermostat housing
- Advice** Nearside Front Outer Tyre slightly damaged side wall (5.2.3 (d) (ii))
- Advice** Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened worn (1.1.14 (a) (ii))
- Minor** Offside Front Windscreen damaged but not adversely affecting driver's view stone chip (3.2 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement back bush (5.3.4 (a) (i))
- Advice** Front slight knocking from steering
- Advice** Nearside Rear Exhaust mounting defective last rear silencer rubber mount bonding worn (6.1.2 (a))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened worn (1.1.14 (a) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement back bush (5.3.4 (a) (i))

MOT #2

2021-09-17 10:03

MOT test number

722150907281

Result

✓ Passed

MOT #1

2020-10-15 08:05

MOT test number

130740369449

Result

✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
17 October 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	17 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2017-10-30
Last registration	2023-10-05
Complete history	See info



Registration #1	2017-10-30	11 mi
Registration #2	2020-10-15	41.443 mi
Registration #3	2023-10-05	55.277 mi
Registration #4	2023-10-05	55.277 mi
Registration #5	2023-10-05	55.277 mi
Registration #6	2023-10-05	55.277 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1826 mm
Height	1644 mm
Length	4597 mm
Wheel base	2840 mm
Kerb weight	1347 kg
Max. allowed weight	2175 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JCAN3042659