



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 D5 SE EU4
Colour	Green
Year of manufacture	2006
Top speed	140 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	27.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	37.7 mpg
CO2 emission	199 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-07-07
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-19
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	32
Total items failed	8

MOT #18	2023-07-20 07:10
MOT test number	442740579280
Result	✓ Passed
Next expiry date	2024-07-19

MOT #17	2022-04-28 08:39
MOT test number	120289498353
Result	✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake slack adjuster advise adjustment (1.1.18 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**MOT #16**

2021-05-27 15:52

MOT test number

134953102101

Result

✓ Passed

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front (5.3.4 (a) (i))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15

2019-12-16 16:54

MOT test number

426097407524

Result

✓ Passed

Advice

Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

MOT #14

2019-01-17 14:37

MOT test number

620343958606

Result

✓ Passed

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Front bush (5.3.4 (a) (i))

MOT #13

2019-01-17 09:44

MOT test number

782455161294

Result

✗ Failed

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Front bush (5.3.4 (a) (i))

MAJOR

Parking brake efficiency below requirements (1.4.2 (a) (i))

MAJOR

Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

MAJOR

Offside Rear Lower Position lamp not working (4.2.1 (a))

**MOT #12** 2018-01-12 10:08**MOT test number** 344143340718**Result** ✓ Passed**MOT #11** 2018-01-11 11:11**MOT test number** 484799267046**Result** ✗ Failed

- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Advice** Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Inner Tyre has ply or cords exposed (4.1.D.1b)

MOT #10 2017-01-11 12:02**MOT test number** 756032713071**Result** ✓ Passed**MOT #9** 2016-01-04 09:23**MOT test number** 332603836921**Result** ✓ Passed**MOT #8** 2015-01-02 15:04**MOT test number** 185512905457**Result** ✓ Passed

- Advice** Offside Front Brake hose slightly chafed (3.6.B.4d)
- Advice** Nearside Front Brake hose slightly chafed (3.6.B.4d)
- Notice** Both front tyres wearing on inner edges.

**MOT #7**

2015-01-02 15:04

MOT test number

166612605474

Result**✗ Failed****Advice** Offside Front Brake hose slightly chafed (3.6.B.4d)**Notice** Both front tyres wearing on inner edges.**Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Brake hose slightly chafed (3.6.B.4d)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)**MOT #6**

2014-01-02 12:01

MOT test number

959292904081

Result**✓ Passed****Advice** Offside Front Brake hose slightly chafed (3.6.B.4d)**Advice** Nearside Front Brake hose slightly chafed (3.6.B.4d)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #5**

2014-01-02 12:01

MOT test number

568432504025

Result**✗ Failed****Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Pass with rectification** Offside Front Direction indicators incorrect colour (1.4.A.2f)**Advice** Offside Front Brake hose slightly chafed (3.6.B.4d)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Brake hose slightly chafed (3.6.B.4d)



MOT #4	2012-12-18 11:09
MOT test number	198483752359
Result	✓ Passed
MOT #3	2011-12-21 10:50
MOT test number	785335751338
Result	✓ Passed
Advice	Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
MOT #2	2010-12-22 12:15
MOT test number	940746350370
Result	✓ Passed
MOT #1	2009-12-21 13:25
MOT test number	473115659346
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
19 July 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	19 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-12-29
Last registration	2023-07-20
Complete history	See info



Registration #1	2006-12-29	26 mi
Registration #2	2009-12-21	15.814 mi
Registration #3	2010-12-22	22.505 mi
Registration #4	2011-12-21	28.234 mi
Registration #5	2012-12-18	36.819 mi
Registration #6	2014-01-02	43.216 mi
Registration #7	2015-01-02	50.698 mi
Registration #8	2016-01-04	57.471 mi
Registration #9	2017-01-11	64.654 mi
Registration #10	2018-01-11	71.837 mi
Registration #11	2019-01-11	79.020 mi
Registration #12	2020-01-11	86.203 mi
Registration #13	2021-01-11	93.386 mi
Registration #14	2022-01-11	100.569 mi
Registration #15	2023-01-11	107.752 mi
Registration #16	2024-01-11	114.935 mi
Registration #17	2025-01-11	122.118 mi
Registration #18	2026-01-11	129.301 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2050 mm
Height	1428 mm
Length	4603 mm
Wheel base	2715 mm
Kerb weight	1519 kg
Max. allowed weight	2050 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	417262