





report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA 12V EXPRESSION TWINPORT
Colour	Blue
Year of manufacture	2007
Top speed	88 mph
0 - 60 mph	16.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	58 BHP
Max. torque	85 Nm at 3.800 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-07-26

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-11-24
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	10
Total items failed	4

MOT #17	2023-11-14 09:49
MOT test number	816358861794
Result	✓ Passed
Next expiry date	2024-11-24

MOT #16	2022-11-24 16:57
MOT test number	985563425674
Result	✓ Passed

MOT #15	2021-11-25 13:02
MOT test number	419152466518
Result	✓ Passed

Advice Nearside Rear Valve stem slightly misaligned being pushed by wheel trim (5.2.3 (j))

Advice Rear Brake pipe corroded, covered in grease or other material both sides corroded at hose (1.1.11 (c))

Advice Offside Front Tyre worn close to legal limit/worn on edge tyre starting to wear on inner edge (5.2.3 (e))

MOT #14	2	2020-09-30 09:35
MOT test	number	355543363971
Result		✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 3/13



MOT #13 2019-09-24 09:36

MOT test number 144768090274

Advice Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #12 2018-10-17 13:19

MOT test number 381152211345

Result
✓ Passed

MOT #11 2018-10-17 13:19

MOT test number 607062584365

Result X Failed

Pass with rectification Offside Headlamp aim too low (4.1.2 (a))

MOT #10 2017-08-11 13:57

MOT test number 246437785914

Advice Offside Front Oil leak oil pressure switch

MOT #9 2016-08-10 12:16

MOT test number 522533312945

Result ✓ Passed

MOT #8 2016-08-10 12:16

MOT test number 307573630976

Result X Failed

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively both sides

(8.2.2)

CarCheck.co.uk page 4/13



Result

MOT #6

Result

RRO7PJR report date: 2024-03-29

✓ Passed

× Failed

2015-08-06 10:07

MOT #7 2015-08-06 10:07
MOT test number 375022319361

MOT test number 357440371725

55744057172

Pass with rectification Nearside Front Headlamp aim too low (1.8)

Pass with rectification Offside Front Headlamp aim too low (1.8)

MOT #5 2014-10-20 13:09

MOT test number 806913594285

Result \rightarrow Passed

MOT #4 2013-10-23 09:46

MOT test number 377746493240

MOT #3 2012-10-16 11:41

MOT test number 619950692223

Result ✓ Passed

MOT #2 2011-10-17 10:48

MOT test number 876370391253

Result

Passed

Notice Front number plate damaged.

Notice Both rear tyres have cracked sidewalls.

Notice Non obligatory mirror damaged

CarCheck.co.uk page 5/13



MOT #1 2010-10-14 11:18

MOT test number 800567180243

Result ✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	24 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date


Type Type

Damage 2

Category

Date

Туре



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner.	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	IIK NIE
Plate since	
Current registration	NK.
Plate since	
	More info

CarCheck.co.uk page 10/13



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-04-30
Last registration	2023-11-14
Complete history	See info



Registration #1	2007-04-30	9 mi
-		
Registration #2	2010-10-14	14.616 mi
Registration #3	2011-10-17	16.241 mi
Registration #4	2012-10-16	17.509 mi
Registration #5	2013-10-23	18.612 mi
Registration #6	2014-10-20	19.256 mi
Registration #7	2015-08-06	19.314 mi
Registration #8	2015-08-06	19.314 mi
Registration #9	2016-08-10	20.312 mi
Registration #10	2016-08-10	20.312 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.177 es

More info >

CarCheck.co.uk page 12/13



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1940 mm
Height	1660 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	965 kg
Max. allowed weight	1435 kg

Additional information

Fuel tank capacity	41
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	19KZ7461

CarCheck.co.uk page 13/13