





report date: 2024-03-29

### General information

Make	NISSAN
Model	LEAF ACENTA
Colour	Silver
Year of manufacture	2014
Top speed	87 mph
0 - 60 mph	11.5 seconds
Gearbox	1 speed automatic

### Engine & fuel consumption

Power	109 BHP
Max. torque	254 Nm at 2.730 rpm
Cylinders	1
Fuel type	Electricity



CarCheck.co.uk page 1/12



report date: 2024-03-29

### Internet history

### Entry 4

Date 2023-01-04


Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 3

Date	2022-02-02
------	------------

Pictures 46

Listing price <u>View report</u>









source: yesauto.com

Entry 2

Date 2021-02-02

Pictures 10

Listing price <u>View report</u>










source: autoonline.co.uk

### Entry 1


Pictures 41

Listing price <u>View report</u>









source: yesauto.com



report date: 2024-03-29

MOINISTORY		
MOT expiry date		

MOT expiry date	2025-02-05
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	13
Total items failed	9

MOT #10		2024-02-06 16:20
MOT test	number	967800965787
Result		✓ Passed
Next expi	ry date	2025-02-05
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened	ed (1.1.14 (a) (ii))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weake	ned (1.1.14 (a) (ii))

CarCheck.co.uk page 3/12



**Advice** 

**Advice** 

Fail

Fail

Result

PN64ZKP

report date: 2024-03-29

✓ Passed

**MOT #9** 2024-02-03 09:26 **MOT** test number 467777885300 Result × Failed Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) **Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h)) Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure 205/55-16 Fail (5.2.3 (d) (ii)) Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #8 2022-02-08 11:35
MOT test number 234381930902

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #7 2021-03-03 17:57

MOT test number 268248074003

Result

MOT #6 2020-09-09 15:23

MOT test number 177409175575

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

CarCheck.co.uk page 4/12



Fail

PN64ZKP

report date: 2024-03-29

MOT #5

MOT test number

808009150630

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4

MOT test number

Result

Result

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #3
 2018-09-24 14:21

 MOT test number
 297699707077

 Result
 ✓ Passed

 MOT #2
 2018-09-22 09:50

 MOT test number
 157686565391

 Result
 X Failed

Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #1

MOT test number

Result

Advice

Nearside Front N/S/F TYRE CUTS IN TREAD BUT NOT EXPOSING PLY OR CORDS YET. 205/55/16 91V

Advice

Offside Front O/S/F TYRE CUTS IN TREAD NOT EXPOSING PLY OR CORDS YET. 205/55/16 91V

CarCheck.co.uk page 5/12



report date: 2024-03-29

### Tax & MOT check





Tax status	Expired at 8 April 2024
Days left	22 days too late
MOT expiry date	5 February 2025
Full MOT history	See MOT history

CarCheck.co.uk page 6/12



report date: 2024-03-29

### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



furthe scinors

PN64ZKP

report date: 2024-03-29

# For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this NISSAN had different number plates.

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-09-11
Last registration	2024-02-06
Complete history	See info



Registration #1	2014-09-11	20 mi
Registration #2	2017-08-26	23.202 mi
Registration #3	2018-09-22	31.471 mi
Registration #4	2018-09-24	31.491 mi
Registration #5	2019-09-25	42.193 mi
Registration #6	2019-09-25	42.193 mi
Registration #7	2020-09-09	49.790 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.177 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.177 ms

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

### Car features

50225	Air conditionin
50295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	89%
Children	83%
Pedestrian	65%
Safety systems	84%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1770 mm
Height	1550 mm
Length	4445 mm
Wheel base	2700 mm
Kerb weight	1525 kg
Max. allowed weight	1945 kg

# Additional information

Fuel delivery	Not Applicable	
Number of doors	5	
Number of seats	5	
Number of axles Carcheck.co.uk	2	page 12/12