



report date: 2024-03-28

General information

Make	SUZUKI
Model	SX X-EC
Colour	Black
Year of manufacture	2012
Top speed	115 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	156 Nm at 4.400 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	45.6 mpg
CO2 emission	141 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-06-11
Pictures	16
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-16
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	21
Total items failed	10

MOT #13 2024-04-08 15:29

MOT test number 251318389806

Result ✓ Passed

Next expiry date 2025-04-16

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #12 2023-03-28 15:00

MOT test number 613859190608

Result ✓ Passed

- Advice** Nearside side mirror movement but still secure
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge and perishing (5.2.3 (e))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #11**

2023-03-23 16:24

MOT test number

859353357365

Result**✗ Failed****Advice**

Offside Front Tyre worn close to legal limit/worn on edge and perishing (5.2.3 (e))

Advice

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Fail

Offside Rear Service brake excessively binding (1.2.1 (f))

Advice

Nearside side mirror movement but still secure

Advice

Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice

Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #10

2022-04-05 14:22

MOT test number

451067378362

Result**✓ Passed****MOT #9**

2021-04-17 08:13

MOT test number

915381810068

Result**✓ Passed**

**MOT #8** 2021-04-08 14:22**MOT test number** 378949682501**Result** ✗ Failed

- Fail** Nearside Front Headlamp aim too high (4.1.2 (a))
- Fail** Offside Front Side repeater with a multiple light source more than 1/2 not functioning (4.4.1 (a) (ii))
- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Offside Front Headlamp aim too high (4.1.2 (a))
- Fail** Nearside Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #7 2020-03-17 08:51**MOT test number** 205600862551**Result** ✓ Passed

- Advice** Offside Side repeater slightly discoloured (4.4.3 (a))
- Advice** Offside Front Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Front Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #6 2019-02-26 11:04**MOT test number** 272218190709**Result** ✓ Passed**MOT #5** 2018-03-13 10:35**MOT test number** 750954336653**Result** ✓ Passed

**MOT #4** 2017-03-16 11:06**MOT test number** 126015186079**Result** ✓ Passed**MOT #3** 2017-03-16 11:06**MOT test number** 688213289500**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #2** 2016-03-21 10:59**MOT test number** 425063794619**Result** ✓ Passed**MOT #1** 2015-03-02 11:40**MOT test number** 315761765070**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
16 April 2025

Tax status	Valid until 1 June
Days left	34
MOT expiry date	16 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	EK12GDE
Plate since	2019-09-28
Current registration	EK12GDE
Plate since	2019-09-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-03-24
Last registration	2024-04-08
Complete history	See info



Registration #1	2012-03-24	7 mi
Registration #2	2015-03-02	27.651 mi
Registration #3	2016-03-21	35.255 mi
Registration #4	2017-03-16	42.004 mi
Registration #5	2017-03-16	42.004 mi
Registration #6	2018-03-13	48.606 mi
Registration #7	2019-02-26	53.744 mi
Registration #8	2020-03-17	60.187 mi
Registration #9	2020-03-17	60.187 mi
Registration #10	2020-03-17	60.187 mi
Registration #11	2020-03-17	60.187 mi
Registration #12	2020-03-17	60.187 mi
Registration #13	2020-03-17	60.187 mi
Registration #14	2020-03-17	60.187 mi
Registration #15	2020-03-17	60.187 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1730 mm
Height	1555 mm
Length	4120 mm
Wheel base	2500 mm
Kerb weight	1240 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-1651017