





report date: 2024-03-28

#### General information

Make	VOLKSWAGEN
Model	PASSAT GT TDI BLUEMOTION TECHNOLOGY
Colour	Blue
Year of manufacture	2017
Top speed	135 mph
0 - 100 km/h	8.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	67.3 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

#### Entry 1

Date 2022-08-01

Pictures 2

Listing price View report





source: cargurus.co.uk

CarCheck.co.uk page 2/11



DE67HLP report date: 2024-03-28

MOT history

MOT expiry date	2024-09-25
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	7
Total items failed	2

MOT #5		2023-09-02 09:54
MOT test	number	463704961024
Result		✓ Passed
Next expi	ry date	2024-09-25
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #4	2022-09-26 08:58
MOT test number	753676624358
Result	<b>✓</b> Passed

Result		V 1 d33Cd
MOT #3		2021-07-23 09:41
MOT test	number	560559081904
Result		✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weak	kened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously we	akened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number
966090939009

Result

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #1

MOT test number

Result

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check





Expires: 25 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	25 September 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



#### Extra VOLKSWAGEN salvage check



**Category** 

**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

**DE67HLP** 

report date: 2024-03-28

# For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report here.

# Plate changes

See in this check if this VOLKSWAGEN had different number plates.

The second s

More info >

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-10-04
Last registration	2023-09-02
Complete history	See info



Registration #1	2017-10-04	26 mi
Registration #2	2020-07-24	61.294 mi
Registration #3	2021-07-23	86.999 mi
Registration #4	2021-07-23	86.999 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		D.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

#### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	85%
Children	87%
Pedestrian	66%
Safety systems	76%
Overall rating	80%
Video	see crash video



# Dimensions & weight

Width	1832 mm
Height	1477 mm
Length	4767 mm
Wheel base	2712 mm
Kerb weight	1505 kg
Max. allowed weight	2100 kg

# Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
CarChack co.uk	nage 11/11

CarCheck.co.uk page 11/11

Number of axles	2
Engine number	CRLB704765