





report date: 2024-03-29

General information

| Make | NISSAN |
|---------------------|---------------------|
| Model | PULSAR ACENTA DIG-T |
| Colour | Beige |
| Year of manufacture | 2015 |
| Top speed | 118 mph |
| 0 - 60 mph | 10.8 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 115 BHP |
|-------------------------|---------------------|
| Max. torque | 190 Nm at 2.000 rpm |
| Engine capacity | 1.198 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 44.8 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 56.5 mpg |
| CO2 emission | 117 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/12



Internet history

Entry 1

| Date | 2021-10-16 | |
|---------------|-------------|--|
| Pictures | 1 | |
| Listing price | View report | |



source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2025-04-18 |
|--------------------|------------|
| MOT pass rate | 78 % |
| MOT passed | 7 |
| Failed MOT tests | 2 |
| Total advice items | 12 |
| Total items failed | 3 |

| MOT #9 | | 2024-04-19 16:57 |
|-----------|--|------------------|
| MOT test | number | 848628051196 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-04-18 |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i)) | |

| MOT #8 | 2023-04-13 09:11 |
|--|------------------|
| MOT test number | 877036922884 |
| Result | ✓ Passed |
| | |
| MOT #7 | 2023-04-12 17:03 |
| MOT test number | 638159635877 |
| Result | X Failed |
| Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Advice Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Minor Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i)) | |

CarCheck.co.uk page 3/12



·

MOT #6 2022-09-26 07:00

MOT test number 944327139468

Result
✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2021-10-27 15:22

MOT test number 611948369506

Result ✓ Passed

MOT #4 2021-01-06 14:05

MOT test number 876987123340

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

MOT #3 2021-01-06 10:10

MOT test number 661565594818

Result X Failed

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

MOT #2 2019-06-12 09:43

MOT test number 583733769812

Result

Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

Result

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 April |
|------------------|---------------------|
| Days left | 336 |
| MOT expiry date | 18 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

| Owner | history |
|-------|---------|

| For how long did the current and previous owner(s) have this NISSAN? How many owner have? Check it in the premium report and see all owner registrations. Download the full | |
|---|-------------|
| | |
| | |
| | |
| | |
| | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this NISSAN had different number plates. | |
| Number of plates | |
| Current registration | NK WE WAS |
| Plate since | |
| Current registration | NK SIK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 9/12



VR15UV

report date: 2024-03-29

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 11 |
| First mileage registration | 2015-05-31 |
| Last registration | 2024-04-19 |
| Complete history | See info |



| Registration #1 | 2015-05-31 | 16 mi |
|------------------|------------|-----------|
| Registration #2 | 2018-05-29 | 23.522 mi |
| Registration #3 | 2019-06-12 | 29.434 mi |
| Registration #4 | 2021-01-06 | 37.110 mi |
| Registration #5 | 2021-01-06 | 37.114 mi |
| Registration #6 | | 0.00 44 |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 0.77 44 |
| Registration #11 | | 10.777 au |

More info >

CarCheck.co.uk page 11/12



Car features

| The NISSAN factory car options list is only available in the premium report. | | | |
|--|------------------|--|--|
| S0225 | Air conditioning | | |
| S0295 | | | |
| S0482 | | | |
| S0501 | | | |
| S0566 | | | |
| S0567 | | | |
| S0569 | | | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 84% |
| Children | 81% |
| Pedestrian | 75% |
| Safety systems | 68% |
| Overall rating | 78% |
| Video | see crash video |

View the complete NISSAN factory list for this vehicle <u>here</u>.



More info >

Dimensions & weight

| Width | 1768 mm |
|---------------------|---------|
| Height | 1520 mm |
| Length | 4385 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1304 kg |
| Max. allowed weight | 1750 kg |

Additional information

| Fuel tank capacity | 46 I | |
|-----------------------------------|------------------|------------|
| Fuel delivery | Direct Injection | |
| Number of doors | 5 | |
| Number of seats CarCheck.co.uk | 5 | page 12/12 |

Number of axles 2

Engine number 136994A