





General information

Make	VOLVO
Model	S40 D R-DESIGN
Colour	Blue
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G







Internet history

Entry 3

Date Pictures 2023-08-27

24

Listing price

View report









source: cargurus.co.uk

Entry 2

Date


Pictures

Listing price

46

2021-09-24

View report



source: cargurus.co.uk

Entry 1

Entry 1	
Date	2021-09-24
Pictures	46
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-20
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	6
Total items failed	3

MOT #13	2023-10-21 16:29
MOT test number	442733202922
Result	✓ Passed
Next expiry date	2024-10-20

MOT #12	2022-09-30 15:47
MOT test number	807942924052
Result	🗸 Passed
Advice Offside Front Suspension arm pin or bush worn but not resulting in ex (i))	cessive movement (5.3.4 (a)
Advice Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in (a) (i))	excessive movement (5.3.4
Advice Nearside Front Suspension arm pin or bush worn but not resulting in a (a) (i))	excessive movement (5.3.4
Advice Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting (5.3.4 (a) (i))	in excessive movement
Advice Nearside Front Tyre worn close to legal limit/worn on edge wearing or	n both edges (5.2.3 (e))

MOT #11	2021-05-08 11:26
MOT test number	468275212997
Result	✓ Passed





MOT #10		2021-05-07 11:33
MOT test number		875083743146
Result		🗙 Failed
Pass with rectification	Rear Registration plate insecure (0.1 (a))	
Fail Offside Rear Tyre h	as ply or cords exposed (5.2.3 (d) (ii))	

MOT #9	2020-05-22 11:52
MOT test number	174608668981
Result	✓ Passed
MOT #8	2019-03-25 12:06
MOT test number	681919038760
Result	✓ Passed
MOT #7	2019-03-25 12:06
MOT test number	477885652156
Result	× Failed
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #6	2018-03-28 13:47
MOT test number	559964055972
Result	✓ Passed
MOT #5	2017-03-30 15:31
MOT test number	167708640780
Result	✓ Passed

MOT #4	2016-03-21 14:42
MOT test number	175080098556
Result	✓ Passed





MOT #3	2015-03-30 13:53
MOT test number	798559385032
Result	✓ Passed
MOT #2	2014-03-27 12:03
MOT test number	707046384058
Result	✓ Passed
Notice Nail in offside front tyre	
MOT #1	2013-03-25 13:07
MOT test number	786244183032
Result	✓ Passed



Tax & MOT check

√ Taxed	√ МОТ
Tax due: 1 December 2024	Expires: 20 October 2024
Tax status	Valid until 1 December
Days left	216
MOT expiry date	20 October 2024
Full MOT history	<u>See MOT history</u>

Tax calculation	

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4 ARAPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-27
Last registration	2023-10-21
Complete history	See info



Registration #1	2010-03-27	11 mi
Registration #2	2013-03-25	9.766 mi
Registration #3	2014-03-27	12.429 mi
Registration #4	2015-03-30	15.138 mi
Registration #5	2016-03-21	18.317 mi
Registration #6	2017-03-30	21.845 mi
Registration #7	2018-03-28	25.506 mi
Registration #8	2019-03-25	28.872 mi
Registration #9	2019-03-25	28.872 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1493 kg
Max. allowed weight	1960 kg
Additional information	
Fuel tank capacity	52 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	732161