



WV08VKH

report date: 2024-03-28

General information

Make	FIAT
Model	BRAVO ACTIVE TJET
Colour	Grey
Year of manufacture	-
Top speed	132 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	206 Nm at 2.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-22
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #18 2022-08-27 08:25

MOT test number 292626019456

Result ✓ Passed

Next expiry date 2023-08-26

- Minor

Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Minor

Offside Front Brake hose slightly damaged (1.1.12 (b) (i))
- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor

Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice

Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #17**

2022-08-22 16:14

MOT test number

570106490927

Result**✗ Failed**

MAJOR Nearside Outer Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MAJOR Nearside Front Brake hose excessively twisted (1.1.12 (b) (ii))

DANGEROUS Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

MAJOR Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Minor Offside Front Brake hose slightly damaged (1.1.12 (b) (i))

Advice Front Service brake fluctuating, but not excessively (1.2.1 (e))

MAJOR Nearside Front Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))

MAJOR Offside Front Brake hose excessively twisted (1.1.12 (b) (ii))

MAJOR Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Offside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))

Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16**

2021-08-04 16:13

MOT test number

781687681079

Result

✓ Passed

- Advice** Rear Exhaust mounting defective insecure (6.1.2 (a))
- Advice** Items removed from driver's view prior to test
- Advice** Rear Tyre slightly damaged/cracking or perishing Both starting to perish (5.2.3 (d) (ii))
- Advice** Nearside Outer Seat belt anchorage prescribed area is corroded but not considered excessive Sill (7.1.1 (a) (i))

MOT #15

2020-08-25 10:46

MOT test number

231177938854

Result

✓ Passed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced VARIOUS POINTS OF FLOOR PAN AND SUSPENSION COMPONENTS CORRODED (6.1.1 (c) (i))
- Advice** WINDSCREEN CRACKED UPPER SECTION
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Coil spring worn BOTH SPRINGS (5.3.1 (b) (i))
- Advice** Offside Rear HAND BRAKE CABLE OUTER COVERING SPLIT
- Advice** REAR EXHAUST BOX CORRODED/ HANGERS

**MOT #14** 2019-08-06 10:50**MOT test number** 261695126107**Result** ✓ Passed**Advice** Offside Rear outer hand brake cable cover split**Advice** Child seats fitted**Advice** Rear exhaust box corroded**Advice** Nearside Front Upper screen cracked**Advice** All tires perished in tread lines**MOT #13** 2018-07-27 13:42**MOT test number** 733347661381**Result** ✓ Passed**MOT #12** 2018-07-26 14:56**MOT test number** 439629728657**Result** ✗ Failed**MAJOR** Nearside Headlamp aim too high (4.1.2 (a))**MOT #11** 2017-08-15 10:22**MOT test number** 580524827010**Result** ✓ Passed**Advice** Windscreen damaged n/s upper out of view**Advice** Exhaust rear box/cover corroded

**MOT #10** 2017-08-15 09:34**MOT test number** 772111300820**Result** ✗ Failed**Fail** Rear Exhaust system not adequately supported joint clamp corroded away missing (7.1.1)**Advice** Windscreen damaged n/s upper out of view**Advice** Exhaust rear box/cover corroded**MOT #9** 2016-08-18 11:05**MOT test number** 249454494403**Result** ✓ Passed**Advice** Exhaust corroded**MOT #8** 2015-08-17 10:04**MOT test number** 922237880513**Result** ✓ Passed**Advice** Rear brake pads worn low**Advice** Exhaust rear section in poor condition**MOT #7** 2014-08-23 10:28**MOT test number** 959285634296**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**Notice** Various suspension components corroded**Notice** Under-trays fitted obscuring some underside components**Notice** Rear silencer and clamp deteriorated**Notice** Rear brake pads appear low

**MOT #6** 2014-08-23 10:28**MOT test number** 645545234257**Result** ✗ Failed**Notice** Items removed from driver's view prior to test**Pass with rectification** Nearside Headlamp aim too low (1.8)**Notice** Various suspension components corroded**Notice** Under-trays fitted obscuring some underside components**Notice** Rear silencer and clamp deteriorated**Notice** Rear brake pads appear low**MOT #5** 2013-08-21 11:21**MOT test number** 525273633299**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #4** 2013-08-20 15:23**MOT test number** 239482933247**Result** ✗ Failed**Fail** Front passenger door cannot be opened from inside the vehicle (6.2.B.1b)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #3** 2012-08-14 13:28**MOT test number** 355867122285**Result** ✓ Passed

**MOT #2** 2011-08-18 09:14**MOT test number** 799540631282**Result** ✓ Passed

- Notice** Front and rear brake pads low
- Notice** Damage on o/s/f corner
- Notice** Rear suspension road springs slight corrosion
- Notice** Various marks and scratches on vehicle and wheel trims
- Notice** Exhaust corroded rear silencer outer casing coming adrift

MOT #1 2011-08-18 09:14**MOT test number** 587720231296**Result** ✗ Failed

- Notice** Various marks and scratches on vehicle and wheel trims
- Notice** Exhaust corroded rear silencer outer casing coming adrift
- Notice** Front and rear brake pads low
- Pass with rectification** Offside Front Valve stem seriously misaligned (4.1.D.1e)
- Notice** Damage on o/s/f corner
- Notice** Rear suspension road springs slight corrosion



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	WV08VKH
Plate since	2019-09-29
Current registration	WV08VKH
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-03-31
Last registration	2022-08-27
Complete history	See info



Registration #1	2008-03-31	26 mi
Registration #2	2011-08-18	26.113 mi
Registration #3	2012-08-14	35.478 mi
Registration #4	2013-08-20	45.320 mi
Registration #5	2013-08-21	45.320 mi
Registration #6	2014-08-23	52.506 mi
Registration #7	2015-08-17	55.366 mi
Registration #8	2016-08-18	58.069 mi
Registration #9	2017-08-15	59.581 mi
Registration #10	2018-08-15	61.093 mi
Registration #11	2019-08-15	62.605 mi
Registration #12	2020-08-15	64.117 mi
Registration #13	2021-08-15	65.629 mi
Registration #14	2022-08-27	67.141 mi
Registration #15	2023-08-15	68.653 mi
Registration #16	2024-03-28	70.165 mi
Registration #17	2024-03-28	71.677 mi
Registration #18	2024-03-28	73.189 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1275 kg
Max. allowed weight	1785 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1148842