



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOUAREG V6 ALTITUDE TDI
Colour	Black
Year of manufacture	2009
Top speed	136 mph
0 - 60 mph	7.8 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	242 BHP
Max. torque	550 Nm at 2.750 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	43.5 mpg
Consumption combined	39.2 mpg
CO2 emission	262 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-09-23
Pictures	4
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-10
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	18
Total items failed	17

MOT #16 2024-02-07 11:26

MOT test number 144494905020

Result ✓ Passed

Next expiry date 2025-02-10

- Advice** Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Central Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #15 2023-02-09 12:10

MOT test number 734364356140

Result ✓ Passed

- Advice** Nearside Front Upper Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Central Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #14** 2022-02-11 17:07**MOT test number** 731406405741**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #13** 2021-06-04 11:09**MOT test number** 803217858967**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2021-06-03 11:57**MOT test number** 775813455850**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #11** 2019-06-26 15:15**MOT test number** 664960303168**Result** ✓ Passed

**MOT #10** 2019-06-25 16:24**MOT test number** 677933617140**Result** ✗ Failed

- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #9 2018-07-06 11:00**MOT test number** 537954466850**Result** ✓ Passed**MOT #8** 2018-07-06 11:00**MOT test number** 193385891571**Result** ✗ Failed

- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))
- Pass with rectification** Stop lamp(s) all not working (4.3.1 (a) (iii))
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #7 2017-06-02 11:31**MOT test number** 902458408624**Result** ✓ Passed**MOT #6** 2016-05-12 12:07**MOT test number** 715355363282**Result** ✓ Passed



MOT #5	2016-05-10 11:06
MOT test number	592003348659
Result	✗ Failed
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Registration plate lamp not working (1.1.C.1d)
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Stop lamp not working (1.2.1b)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #4	2015-02-18 18:05
MOT test number	116499345011
Result	✓ Passed

MOT #3	2013-09-02 13:27
MOT test number	299535143292
Result	✓ Passed
Notice	Nail in offside rear tyre
Notice	Vehicle's internal headlight adjuster altered to recheck lights
Notice	Under-trays fitted obscuring some underside components



MOT #2	2013-09-02 13:27
MOT test number	798645443213
Result	✗ Failed
Notice	Under-trays fitted obscuring some underside components
Pass with rectification	Offside Rear Stop lamp not working (1.2.1b)
Notice	Nail in offside rear tyre
Pass with rectification	Nearside Rear Registration plate lamp not working (1.1.C.1d)
Notice	Vehicle's internal headlight adjuster altered to recheck lights

MOT #1	2012-09-12 11:00
MOT test number	907226352282
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
10 February 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	10 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 OV58RFO
Plate since	2024-03-28
Current registration	 OV58RFO
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-01-14
Last registration	2024-02-07
Complete history	See info



Registration #1	2009-01-14	18 mi
Registration #2	2012-09-12	34.619 mi
Registration #3	2013-09-02	43.760 mi
Registration #4	2015-02-18	54.316 mi
Registration #5	2016-05-10	65.521 mi
Registration #6	2016-05-12	65.521 mi
Registration #7	2017-06-02	72.576 mi
Registration #8	2018-07-06	80.524 mi
Registration #9	2018-07-06	80.524 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1940 mm
Height	1732 mm
Length	4795 mm
Wheel base	2893 mm
Kerb weight	2321 kg
Max. allowed weight	2945 kg

Additional information

Fuel tank capacity	85 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CAS 052042