



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 16V
Colour	Red
Year of manufacture	-
Top speed	100 mph
0 - 60 mph	14.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	126 Nm at 3.300 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-09
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history****MOT #16** 2023-08-17 09:38**MOT test number** 440136497972**Result** ✗ Failed

Advice Offside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

MAJOR Nearside Front Lower Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

Advice General corrosion to underside and some components

MAJOR Nearside Rear Lower Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened Pitted (1.1.14 (a) (ii))

MAJOR Offside Front Lower Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

MOT #15 2022-09-13 09:16**MOT test number** 411841303960**Result** ✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14 2022-09-05 08:22**MOT test number** 759637666027**Result** ✗ Failed

MAJOR Nearside Rear Service brake excessively binding (1.2.1 (f))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Offside Rear Service brake excessively binding (1.2.1 (f))

MOT #13 2021-08-14 12:43**MOT test number** 227643199632**Result** ✓ Passed



MOT #12	2020-09-04 17:19
MOT test number	909490292088
Result	✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #11	2020-08-12 07:32
MOT test number	739461580049
Result	✗ Failed
MAJOR	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
MAJOR	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
MAJOR	Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10	2019-08-27 07:37
MOT test number	302407212302
Result	✓ Passed

MOT #9	2019-08-27 07:37
MOT test number	971348932211
Result	✗ Failed
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MOT #8** 2018-08-31 12:11**MOT test number** 976438688731**Result** ✓ Passed**MOT #7** 2017-09-13 13:34**MOT test number** 230964900458**Result** ✓ Passed**MOT #6** 2016-11-26 10:34**MOT test number** 428800271396**Result** ✓ Passed**Advice** Near side front and off side rear tyres cracked and perished.**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-12-11 14:44**MOT test number** 240118218621**Result** ✓ Passed**Advice** Off side front brake disc pitted and corroded on inside edge**Advice** Off side rear tyre cracked and perished

**MOT #4** 2015-12-11 11:06**MOT test number** 124444858486**Result** ✗ Failed**Fail** Front Brakes imbalanced across an axle (3.7.B.5b)**Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Off side rear tyre cracked and perished**Fail** Offside Stop lamp not working (1.2.1b)**Pass with rectification** Offside Headlamp aim too high (1.8)**Advice** Off side front brake disc pitted and corroded on inside edge**MOT #3** 2014-12-19 09:53**MOT test number** 417323554455**Result** ✓ Passed**MOT #2** 2013-11-30 13:33**MOT test number** 426284933308**Result** ✓ Passed**MOT #1** 2012-12-10 10:53**MOT test number** 476215042360**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-12-14
Last registration	2023-08-17
Complete history	See info



Registration #1	2009-12-14	26 mi
Registration #2	2012-12-10	17.440 mi
Registration #3	2013-11-30	22.912 mi
Registration #4	2014-12-19	26.682 mi
Registration #5	2015-12-11	33.337 mi
Registration #6	2015-12-11	33.337 mi
Registration #7	2016-11-26	38.961 mi
Registration #8	2017-09-13	45.758 mi
Registration #9	2018-08-31	51.520 mi
Registration #10	2019-05-29	55.277 mi
Registration #11	2019-05-29	55.277 mi
Registration #12	2019-05-29	55.277 mi
Registration #13	2019-05-29	55.277 mi
Registration #14	2019-05-29	55.277 mi
Registration #15	2019-05-29	55.277 mi
Registration #16	2019-05-29	55.277 mi
Registration #17	2019-05-29	55.277 mi
Registration #18	2019-05-29	55.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2515 mm
Kerb weight	1285 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BCA 568410