





report date: 2024-03-29

General information

Make	AUDI
Model	A3 TFSI SPORT
Colour	Blue
Year of manufacture	2008
Top speed	144 mph
0 - 60 mph	7.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	197 BHP
Max. torque	280 Nm at 1.800 rpm
Engine capacity	1.984 сс
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.2 mpg
CO2 emission	182 g/km
CO2 label	I



CarCheck.co.uk page 1/12



MOT history

MOT expiry date	2025-01-29
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	23
Total items failed	6

MOT #14	2024-01-30 13:54
MOT test number	399027901532
Result	✓ Passed
Next expiry date	2025-01-29
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #13	2024-01-19 17:45	
MOT test number	823176436912	
Result	X Failed	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Fail Emissions unable to be completed (8.2.1.2 (d))		
Advice Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))		
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))		
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))		
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))		

MOT #12	2022-03-08 12:26
MOT test number	108074091743
Result	✓ Passed

CarCheck.co.uk page 2/12



Result

GU58XBJ report date: 2024-03-29

✓ Passed

 MOT #11
 2021-03-19 18:09

 MOT test number
 117239975073

MOT #10 2019-05-24 11:02

MOT test number 510662473815

•

Advice Nearside Front Tyre worn close to legal limit/worn on edge Outer edge worn. (5.2.3 (e))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge Outer edge worn. (5.2.3 (e))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #9 2019-05-18 14:31

MOT test number 396579560051

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge Outer edge worn. (5.2.3 (e))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Brake fluid contaminated (1.8 (a))

Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge Outer edge worn. (5.2.3 (e))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #8 2018-04-26 15:44

MOT test number 808075340531

Result
✓ Passed

CarCheck.co.uk page 3/12



GU58XBJ

report date: 2024-03-29

MOT #7

MOT test number

2017-02-28 13:33

MOT test number

201822032143

✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

 MOT #6
 2016-03-04 13:54

 MOT test number
 859258950245

 Result
 ✓ Passed

 MOT #5
 2015-03-26 15:53

 MOT test number
 425495585032

 Result
 ✓ Passed

MOT test number 396481344428

Result ✓ Passed

Advice (1.1.A.3b)
Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

Notice Items removed from driver's view prior to test

MOT #3

MOT test number

437619553292

Result

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 4/12



MOT #2

MOT test number

Result

Advice Rear registration plate delaminated but not likely to be misread (6.3.1d)

Notice Slight damage to underside tunnel area

MOT #1	2011-08-02 23:55
MOT test number	637144611201
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	29 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-


CarCheck.co.uk page 6/12



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



_		
Owne	 	
	ΙСΤ	nrv
	 IJL	

,		
For how long did the current and previous owner(s) have this AUDI? How many owners defect it in the premium report and see all owner registrations. Download the full report		e?
2000000		
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		

	More info	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-09-04
Last registration	2024-01-30
Complete history	See info



Registration #1	2008-09-04	14 mi
Registration #2	2011-08-02	21.180 mi
Registration #3	2012-09-03	31.530 mi
Registration #4	2013-09-16	40.690 mi
Registration #5	2014-08-29	50.729 mi
Registration #6	2015-03-26	53.314 mi
Registration #7	2016-03-04	61.294 mi
Registration #8	2017-02-28	70.479 mi
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.177 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1424 mm
Length	4238 mm
Wheel base	2578 mm
Kerb weight	1435 kg
Max. allowed weight	1935 kg

Additional information

Fuel tank capacity	55 I	
Fuel delivery	Direct Injection	
Number of doors	2	
Number of seats CarCheck.co.uk	4 page :	12/12

Number of axles 2

Engine number CAW 001809