



report date: 2024-03-28

General information

Make	NISSAN
Model	ALMERA S
Colour	Grey
Year of manufacture	2004
Top speed	109 mph
0 - 60 mph	12.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	114 BHP
Max. torque	163 Nm at 4.000 rpm
Engine capacity	1.769 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.2 mpg
CO2 emission	187 g/km
CO2 label	J



**MOT history**

MOT expiry date	2021-09-26
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	34
Total items failed	17

MOT #21 2020-09-23 08:41**MOT test number** 997151757047**Result** Passed**Next expiry date** 2021-09-26

Advice Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))

Advice Offside Front Service brake binding but not excessively (1.2.1 (f))

Minor Headlamp lens slightly defective both faded (4.1.1 (b) (i))

MOT #20 2019-09-27 14:48**MOT test number** 590624702423**Result** Passed

Advice Rear Registration plate insecure but not likely to fall off (0.1 (a))

Advice Hydraulic leak, but not excessive around steering rack (8.4.1 (a) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #19**

2019-09-27 09:35

MOT test number

336619892504

Result**✗ Failed**

- Fail** Nearside Headlamp insecure (4.1.1 (c))
- Advice** Rear Registration plate insecure but not likely to fall off (0.1 (a))
- Advice** Hydraulic leak, but not excessive around steering rack (8.4.1 (a) (i))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Rear Exhaust has a major leak of exhaust gases silencer (6.1.2 (a))

MOT #18

2019-03-17 13:36

MOT test number

488382230321

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Fluid leak, but not excessive (8.4.1 (a) (i))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #17** 2018-04-19 16:32**MOT test number** 612710544774**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #16** 2016-10-04 10:14**MOT test number** 340642657955**Result** ✓ Passed**MOT #15** 2016-10-04 10:14**MOT test number** 862499501673**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**MOT #14** 2015-10-12 15:35**MOT test number** 266681187269**Result** ✓ Passed**MOT #13** 2015-10-12 15:35**MOT test number** 821270020998**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #12** 2014-09-06 16:37**MOT test number** 717549644210**Result** ✓ Passed**Notice** Offside front tyre perished**Notice** Near side front tyre perished**Notice** Oil leak

**MOT #11** 2014-09-06 15:03**MOT test number** 138189544209**Result** ✗ Failed**Notice** Near side front tyre perished**Notice** Oil leak**Fail** Nearside Front Headlamp insecure (1.7.3)**Fail** Offside Front Seat belt stitching not secure (5.2.2b)**Notice** Offside front tyre perished**Fail** Offside Front Headlamp not working on main beam (1.7.5a)**Fail** Nearside Front Seat belt stitching not secure (5.2.2b)**MOT #10** 2013-09-04 16:48**MOT test number** 636677743247**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2013-09-04 16:48**MOT test number** 356817743413**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2012-08-31 11:12**MOT test number** 738704742219**Result** ✓ Passed**MOT #7** 2012-08-31 11:12**MOT test number** 167854842230**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #6** 2011-08-25 13:38**MOT test number** 298367931202**Result** ✓ Passed**MOT #5** 2010-08-24 15:09**MOT test number** 284826130213**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2010-08-24 12:53**MOT test number** 500486630237**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2009-08-22 12:13**MOT test number** 174894839294**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2008-08-02 12:32**MOT test number** 104165718263**Result** ✓ Passed**MOT #1** 2007-06-29 12:00**MOT test number** 304520687148**Result** ✓ Passed**Notice** Rear brakes binding**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Rear brakes noisy on brt



Tax & MOT check

✕
Untaxed

Tax expired:
1 April 2021

✕
MOT

Expired:
26 September 2021

Tax status	Expired at 1 April 2021
Days left	1124 days too late
MOT expiry date	26 September 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2004-07-28
Last registration	2020-09-23
Complete history	See info



Registration #1	2004-07-28	17 mi
Registration #2	2007-06-29	25.586 mi
Registration #3	2008-08-02	32.027 mi
Registration #4	2009-08-22	37.856 mi
Registration #5	2010-08-24	43.336 mi
Registration #6	2010-08-24	43.336 mi
Registration #7	2011-08-25	50.340 mi
Registration #8	2012-08-31	57.237 mi
Registration #9	2013-09-04	66.853 mi
Registration #10	2014-09-06	80.850 mi
Registration #11	2015-09-06	95.337 mi
Registration #12	2016-09-06	110.337 mi
Registration #13	2017-09-06	125.337 mi
Registration #14	2018-09-06	140.337 mi
Registration #15	2019-09-06	155.337 mi
Registration #16	2020-09-23	170.337 mi
Registration #17	2021-09-23	185.337 mi
Registration #18	2022-09-23	200.337 mi
Registration #19	2023-09-23	215.337 mi
Registration #20	2024-03-28	230.337 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1199 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	326556