



report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D3 SE LUX
Colour	Silver
Year of manufacture	2013
Top speed	127 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	350 Nm at 2.250 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-03-06
Pictures	24
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2024-10-22
MOT pass rate	100 %
MOT passed	8
Failed MOT tests	0
Total advice items	8
Total items failed	0

MOT #8 2023-10-16 15:57**MOT test number** 707094016097**Result** Passed**Next expiry date** 2024-10-22**Advice** Nearside Rear Inner Tyre slightly damaged/cracking or perishing Badly on inner shoulder (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing Beginning to crack in treads (5.2.3 (d) (ii))**MOT #7** 2022-10-04 16:03**MOT test number** 429750523995**Result** Passed**Advice** Items removed from driver's view prior to test**MOT #6** 2021-10-23 05:21**MOT test number** 290154217403**Result** Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #5** 2020-08-24 13:11**MOT test number** 983857040224**Result** Passed

**MOT #4** 2019-04-10 14:35**MOT test number** 380824293122**Result** ✓ Passed

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face partially pitting (1.1.14 (a) (ii))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm void bush starting to separate/deteriorate (5.3.4 (a) (i))

MOT #3 2018-04-19 09:39**MOT test number** 608377282689**Result** ✓ Passed**MOT #2** 2017-04-07 09:37**MOT test number** 997196897506**Result** ✓ Passed**MOT #1** 2016-04-26 13:56**MOT test number** 694509092673**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
22 October 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	22 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2013-04-30
Last registration	2023-10-16
Complete history	See info



Registration #1	2013-04-30	26 mi
Registration #2	2016-04-26	21.751 mi
Registration #3	2017-04-07	28.802 mi
Registration #4	2018-04-19	37.720 mi
Registration #5	2019-04-10	46.581 mi
Registration #6	2020-04-20	55.442 mi
Registration #7	2021-04-20	64.303 mi
Registration #8	2022-04-20	73.164 mi
Registration #9	2023-04-20	82.025 mi
Registration #10	2023-10-16	90.886 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1605 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	1259958
---------------	---------