






report date: 2024-03-28

General information

Make	FIAT
Model	DOBLO 16V MULTIJET
Colour	White
Year of manufacture	2013
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry	1

Entry 2	
Date	2021-10-29
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-11-10
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	14
Total items failed	8

MOT #12	2023-10-31 11:48
MOT test number	928498171317
Result	✓ Passed
Next expiry date	2024-11-10
Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))	

MOT #11	2022-11-08 12:00
MOT test number	665859624629
Result	✓ Passed

MOT #10	2022-11-07 11:28
MOT test number	997581233272
Result	X Failed
Fail Front Windscreen washer provides insufficient washer liquid both sid	des (3.5 (a))
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover no lon (5.3.4 (b) (ii))	nger prevents the ingress of dirt

MOT #9	2021-11-11 16:26
MOT test number	680017503299
Result	✓ Passed
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #8 2020-11-05 15:09 **MOT** test number 183053187101 ✓ Passed Result Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Rear Direction indicator slightly discoloured (4.4.3 (a)) Advice Advice Nearside Front Child Seat fitted not allowing full inspection of adult belt

MOT #7 2020-11-03 12:22 664751011421 **MOT test number** Result ★ Failed **Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Nearside Rear Lower Shock absorbers has an excessively worn bush (5.3.2 (c)) **Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Fail Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

MOT #6	2019-11-09 12:12
MOT test number	324777769422
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5 2019-06-20 14:30

MOT test number 455908352331

MOT #4 2019-06-18 08:34

MOT test number 579611777617

Result × Failed

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #3 2018-07-31 08:28

MOT test number 315089000051

Result \rightarrow Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #2 2017-02-23 17:08

MOT test number 270014459477

Advice Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)

MOT #1 2016-03-14 12:01

MOT test number 272166897303

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check





Expires: 10 November 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	10 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



WV13EHM
report date: 2024-03-28

·

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report $\underline{\mathbf{k}}$:?

	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		
Current registration	NK SIE	
Plate since		
Current registration	NK NY	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



VV13EHM

report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-05
Last registration	2023-10-31
Complete history	See info



Registration #1	2013-03-05	19 mi
Registration #2	2016-03-14	51.909 mi
Registration #3	2017-02-23	58.776 mi
Registration #4	2018-07-31	72.772 mi
Registration #5	2019-06-18	79.315 mi
Registration #6	2019-06-20	79.315 mi
Registration #7	2019-11-09	84.694 mi
Registration #8		77.777-00
Registration #9		77.777 46
Registration #10		77.777 44
Registration #11		77.777 46
Registration #12		77.777-00
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	4945767

CarCheck.co.uk page 12/12