



report date: 2024-03-29

## General information

|                     |                    |
|---------------------|--------------------|
| Make                | VAUXHALL           |
| Model               | AGILA S AC ECOFLEX |
| Colour              | Red                |
| Year of manufacture | 2013               |
| Top speed           | 99 mph             |
| 0 - 60 mph          | 14.2 seconds       |
| Gearbox             | 5 speed Manual     |

## Engine & fuel consumption

|                         |                    |
|-------------------------|--------------------|
| Power                   | 67 BHP             |
| Max. torque             | 90 Nm at 4.800 rpm |
| Engine capacity         | 996 cc             |
| Cylinders               | 3                  |
| Fuel type               | Petrol             |
| Consumption city        | 50.4 mpg           |
| Consumption extra urban | 65.7 mpg           |
| Consumption combined    | 58.9 mpg           |
| CO2 emission            | 109 g/km           |
| CO2 label               | B                  |





MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2025-01-17 |
| MOT pass rate      | 82 %       |
| MOT passed         | 9          |
| Failed MOT tests   | 2          |
| Total advice items | 16         |
| Total items failed | 3          |

|                  |  |
|------------------|--|
| MOT #11          | 2024-01-12 09:26   |
| MOT test number  | 195044717901   |
| Result           | ✓ Passed   |
| Next expiry date | 2025-01-17   |
| Advice           | Offside Rear Direction indicator slightly discoloured (4.4.3 (a))                  |
| Advice           | Nearside Rear Fuel Pipe/s corroded Front to rear section                           |
| Advice           | Nearside Oil leak, but not excessive Gearbox driveshaft oil seal (8.4.1 (a) (i))   |
| Advice           | Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))                 |
| Advice           | Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) |

|                 |  |
|-----------------|--|
| MOT #10         | 2023-01-17 15:08   |
| MOT test number | 238349411740   |
| Result          | ✓ Passed   |
| Advice          | Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) |
| Advice          | Nearside Rear Fuel Pipe/s corroded   |

**MOT #9** 2023-01-13 13:52**MOT test number** 348593179298**Result** ✗ Failed**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Advice** Nearside Rear Fuel Pipe/s corroded**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #8** 2022-01-14 15:34**MOT test number** 985085674248**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #7** 2022-01-14 10:36**MOT test number** 463715411963**Result** ✗ Failed**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #6** 2021-01-18 09:59**MOT test number** 914270094615**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #5** 2020-03-14 10:09**MOT test number** 759521123173**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #4** 2019-03-16 09:57**MOT test number** 219737772010**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2018-03-12 12:49**MOT test number** 887283718675**Result** ✓ Passed**MOT #2** 2017-03-16 09:06**MOT test number** 194316844266**Result** ✓ Passed**MOT #1** 2016-05-23 07:45**MOT test number** 457156210656**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
17 January 2025

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 April             |
| <b>Days left</b>        | 337                             |
| <b>MOT expiry date</b>  | 17 January 2025                 |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |                |
|--|----------------|
| <b>Vehicle class</b>                           | 48             |
| <b>Band</b>                                    | B              |
| <b>Single payment (12 months)</b>              | £ 20,00,-      |
| <b>Single six month payment</b>                | Not applicable |
| <b>Total payable by 12 monthly instalments</b> | £ 21,00,-      |



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration | ND13UYY    |
| Plate since          | 2019-03-29 |
| Current registration | ND13UYY    |
| Plate since          | 2019-03-29 |

More info >





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

|                   |          |          |
|-------------------|----------|----------|
| Finance company   | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type    | REDACTED | REDACTED |
| Agreement term    | REDACTED | REDACTED |
| Agreement number  | REDACTED | REDACTED |
| Contact info      | REDACTED | REDACTED |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 12                       |
| First mileage registration | 2013-06-19               |
| Last registration          | 2024-01-12               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2013-06-19 | 29 mi     |
| Registration #2  | 2016-05-23 | 26.258 mi |
| Registration #3  | 2017-03-16 | 33.311 mi |
| Registration #4  | 2018-03-12 | 40.323 mi |
| Registration #5  | 2019-03-16 | 47.778 mi |
| Registration #6  | 2020-03-14 | 53.365 mi |
| Registration #7  | 2020-03-14 | 53.365 mi |
| Registration #8  | 2020-03-14 | 53.365 mi |
| Registration #9  | 2020-03-14 | 53.365 mi |
| Registration #10 | 2020-03-14 | 53.365 mi |
| Registration #11 | 2020-03-14 | 53.365 mi |
| Registration #12 | 2020-03-14 | 53.365 mi |

More info >



Safety ratings

|             |                                 |
|-------------|---------------------------------|
| NCAP rating | ★★★★★                           |
| Video       | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1932 mm |
| Height              | 1590 mm |
| Length              | 3740 mm |
| Wheel base          | 2360 mm |
| Kerb weight         | 985 kg  |
| Max. allowed weight | 1485 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 45 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of seats    | 5                     |
| Engine number      | K10B - 1610584LUX     |