





report date: 2024-03-28

# General information

Make	PEUGEOT
Model	508 HDI ALLURE
Colour	Blue
Year of manufacture	2011
Top speed	140 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	163 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	72.4 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D



CarCheck.co.uk page 1/13



report date: 2024-03-28

# Internet history

# Entry 1

Date 2021-08-09

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

N/I	$\alpha$		uc:	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2025-02-13
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	19
Total items failed	3

MOT #13	2024-01-22 09:16
MOT test number	234239658406
Result	✓ Passed
Next expiry date	2025-02-13

MOT #12	2024-01-19 14:26
MOT test number	393598534650
Result	<b>×</b> Failed
Fail Nearside Side repeater light intensity significantly reduced (4.4.3 (a))	

MOT #11		2023-02-14 11:51
MOT test	number	504645731085
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

**MOT #10** 2022-03-23 16:28 **MOT** test number 170819658267 Result ✓ Passed **Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii)) **Advice** Engine bay covers and full undertrays fitted, obscuring full inspection of some components **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii)) **Advice** Nearside Front brake pad wear wire damaged and not connected

**MOT #9** 2022-03-23 09:12 **MOT** test number 328118101283 Result × Failed **Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii)) Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure inner edge (5.2.3 (d) (ii)) **Advice** Engine bay covers and full undertrays fitted, obscuring full inspection of some components **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii)) Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure inner edge (5.2.3 (d) (ii)) **Advice** Nearside Front brake pad wear wire damaged and not connected

MOT test number

Result

Advice
All tyres worn on edges

Advice
Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice
Cracking and perishing to all tyres

Cut to n/s/r tyre outer sidewall

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number

Result

Advice

Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6	2019-03-25 15:41
MOT test number	230456567831
Result	<b>✓</b> Passed
MOT #5	2018-03-09 09:17
MOT test number	694543209835
Result	<b>✓</b> Passed
Advice Offside Rear Nail in tyre	

MOT #4	2017-03-28 15:58
MOT test number	487946369646
Result	<b>✓</b> Passed
Advice Undertrays fitted	

MOT #3	2016-11-25 16:46
MOT test number	875454806827
Result	<b>✓</b> Passed
MOT #2	2015-09-26 08:12
MOT test number	272566628514
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #1 2014-09-27 10:51

**MOT test number** 775070474216

**Result** ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

# Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	13 February 2025
Full MOT history	See MOT history

# Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner	history
O WILCI	,

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full it	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	OK SIE SIE
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-29
Last registration	2024-01-22
Complete history	See info



Registration #1	2011-09-29	17 mi
Registration #2	2014-09-27	27.926 mi
Registration #3	2015-09-26	38.568 mi
Registration #4	2016-11-25	45.049 mi
Registration #5	2017-03-28	45.124 mi
Registration #6	2018-03-09	66.298 mi
Registration #7	2019-03-25	76.323 mi
Registration #8	2020-03-25	89.558 mi
Registration #9		11.177 es
Registration #10		11.777 es
Registration #11		11.177 es
Registration #12		11.177 es
Registration #13		11.177 es
Registration #14		11.777 44
Registration #15		9.77 ss

More info >

CarCheck.co.uk page 12/13



KN61HTE report date: 2024-03-28

Car features

50225	Air conditioni
S0295	
50482	
S0501	
S0566	
S0567	
50569	

# Safety ratings

NCAP rating	****
Adult	90%
Children	87%
Pedestrian	41%
Safety systems	97%
Overall rating	80%
Video	see crash video



# Dimensions & weight

Width	1853 mm
Height	1456 mm
Length	4792 mm
Wheel base	2817 mm
Kerb weight	1675 kg
Max. allowed weight	2075 kg

# Additional information

Fuel tank capacity	72 l	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 pag	je 13/13

Number of axles 2

Engine number DYYF4064600