





report date: 2024-03-29

### General information

Make	FORD
Model	KUGA GHIA TDCI
Colour	Black
Year of manufacture	2009
Top speed	120 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history

### Entry 3

Date 2023-01-14

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

#### Entry 2

Date	2023-01-13

Pictures 9

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history	Μ	OT	h	is	to	rv
-------------	---	----	---	----	----	----

MOT expiry date	2023-02-15
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	15
Total items failed	7

MOT #13	2022-02-14 10:56
MOT test number	437167767253
Result	✓ Passed
Next expiry date	2023-02-15

MOT #12	2021-02-16 17:03	
MOT test	number 716030648511	_
Result	✓ Passed	
Minor	Nearside Front Upper Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #11		2020-02-11 17:15
MOT test	number	597518260881
Result		✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

**MOT #10** 2020-02-11 11:04

MOT test number 104302558611

Result X Failed

**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #9 2018-10-01 12:54

**MOT test number** 708354190953

**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge and sidewall damage (5.2.3 (e))

MOT #8 2017-09-29 13:00

**MOT test number** 464838529337

**Result** ✓ Passed

**MOT #7** 2016-09-27 12:36

MOT test number 347109854911

**Result** ✓ Passed

MOT #6 2016-09-27 08:12

MOT test number 811458394502

**Result** X Failed

**Advice** Engine warning light on

**Fail** Offside Front position lamp(s) not working (1.1.A.3b)

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #5 2015-04-08 13:19

**MOT test number** 866018195042

MOT #4 2015-03-13 06:50

**MOT test number** 167222975045

**Result** ★ Failed

Fail Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Registration plate lamp not working (1.1.C.1d)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2014-05-28 16:43

**MOT test number** 289328344481

**Result** ✓ Passed

MOT #2 2013-05-13 10:26

**MOT test number** 587233533148

**Result** ✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Notice** O/s/r tyre cracking

**MOT #1** 2012-03-17 09:30

**MOT test number** 736097372015

**Result** 
✓ Passed

**Notice** Front & rear brake pads getting low

CarCheck.co.uk page 5/12



report date: 2024-03-29

#### Tax & MOT check

Tax expired: 12 January 2023



Expired: 15 February 2023

**Х** МОТ

Tax status	Expired at 12 January 2023
Days left	473 days too late
MOT expiry date	15 February 2023
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



AKO9ARX report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner	history
O WILCI	,

e which misterly	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
THE PARTY OF THE P	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	OK SIES
Plate since	
	More info >

CarCheck.co.uk page 9/12



**AKO9ARX** report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-03-04
Last registration	2022-02-14
Complete history	See info



Registration #1	2009-03-04	6 mi
Registration #2	2012-03-17	44.932 mi
Registration #3	2013-05-13	55.966 mi
Registration #4	2014-05-28	68.338 mi
Registration #5	2015-03-13	77.896 mi
Registration #6	2015-04-08	77.916 mi
Registration #7	2016-09-27	83.420 mi
Registration #8	2016-09-27	83.420 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 11/12



AKO9ARX report date: 2024-03-29

Car features

The FORD factory car options list is only available in the premium report.		
S0225	Air conditioning	
S0295		
S0482		
S0501		
S0566		
S0567		

View the complete FORD factory list for this vehicle <u>here</u>.

More info >

## Safety ratings

**S0569** 

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1884 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg

### Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Number of axles 2

**Engine number** 9K79192