



report date: 2024-03-29

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Black
Year of manufacture	2010
Top speed	122 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 3.250 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-06-27
Pictures	16
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-31
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	33
Total items failed	12

MOT #18	2023-05-10 10:53
MOT test number	487240710496
Result	✓ Passed
Next expiry date	2024-05-31

MOT #17	2023-05-09 10:16
MOT test number	670479712465
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Nearside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Front Headlamp insecure (4.1.1 (c))

MOT #16	2022-05-04 13:36
MOT test number	170180183735
Result	✓ Passed
Advice	Nearside Front Child Seat fitted not allowing full inspection of adult belt
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #15** 2021-06-01 12:54**MOT test number** 486017561556**Result** ✓ Passed**Advice** Rear Coil spring corroded both sides, only on lower sections (5.3.1 (b) (i))**MOT #14** 2021-05-25 12:19**MOT test number** 505014060504**Result** ✗ Failed**Advice** Exhaust has a minor leak of exhaust gases centre section (6.1.2 (a))**Advice** Front Tyre worn close to legal limit/worn on edge both sides, 225/50R17 (5.2.3 (e))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Rear Coil spring corroded both sides, only on lower sections (5.3.1 (b) (i))**MOT #13** 2020-07-15 09:47**MOT test number** 245858068602**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Coil spring corroded both sides, lower sections (5.3.1 (b) (i))**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Front Tyre worn close to legal limit/worn on edge both sides, worn on edges 225/50R17 (5.2.3 (e))**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement both sides, trailing arm (5.3.4 (a) (i))**MOT #12** 2019-07-11 13:39**MOT test number** 272682096248**Result** ✓ Passed**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #11** 2019-07-11 08:56**MOT test number** 481800218846**Result** ✗ Failed**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #10** 2018-07-13 08:47**MOT test number** 948244197862**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #9** 2017-07-19 08:05**MOT test number** 561284553511**Result** ✓ Passed**MOT #8** 2017-07-17 10:09**MOT test number** 456945773284**Result** ✗ Failed**Fail** Headlamp aim too low both sides (1.8)**Advice** Tyre worn close to the legal limit both sides - rear - tyre size 225 50 17 (4.1.E.1)**MOT #7** 2016-07-15 09:15**MOT test number** 775870807711**Result** ✓ Passed**Advice** Offside Rear Tyre worn on edges but still legal.

**MOT #6** 2016-07-14 13:58**MOT test number** 714431499785**Result** ✗ Failed**Advice** Offside Front tyre worn on tread edges but still legal**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords large split in tread (4.1.D.1a)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-07-09 14:19**MOT test number** 146450995155**Result** ✓ Passed**MOT #4** 2015-07-07 09:45**MOT test number** 819378685148**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Parking brake lever has no reserve travel (3.1.6b)**MOT #3** 2014-07-15 17:38**MOT test number** 788856294126**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components

**MOT #2** 2014-07-15 10:12**MOT test number** 618776994113**Result** ✗ Failed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #1 2013-07-15 10:08**MOT test number** 418936493128**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Nearside front tyre damage
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Offside front tyre wearing on inner edge



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
31 May 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	31 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	LY10JVD
Plate since	2024-03-29
Current registration	LY10JVD
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-07-26
Last registration	2023-05-10
Complete history	See info



Registration #1	2010-07-26	29 mi
Registration #2	2013-07-15	29.573 mi
Registration #3	2014-07-15	41.354 mi
Registration #4	2014-07-15	41.370 mi
Registration #5	2015-07-07	49.591 mi
Registration #6	2015-07-09	49.627 mi
Registration #7	2016-07-14	59.033 mi
Registration #8	2016-07-15	59.040 mi
Registration #9	2017-07-17	68.415 mi
Registration #10	2017-07-19	68.416 mi
Registration #11	2018-05-20	75.277 mi
Registration #12	2018-05-20	75.277 mi
Registration #13	2018-05-20	75.277 mi
Registration #14	2018-05-20	75.277 mi
Registration #15	2018-05-20	75.277 mi
Registration #16	2018-05-20	75.277 mi
Registration #17	2018-05-20	75.277 mi
Registration #18	2018-05-20	75.277 mi
Registration #19	2018-05-20	75.277 mi
Registration #20	2018-05-20	75.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number

AU21080