



report date: 2024-03-28

## General information

Make	VOLVO
Model	S40 D2 R-DESIGN
Colour	Red
Year of manufacture	2011
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C






Internet history

Entry 1

Date	2022-04-24
Pictures	25
Listing price	<a href="#">View report</a>



source: yesauto.com



MOT history

MOT expiry date	2024-06-05
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	17
Total items failed	11

MOT #13	2023-06-06 07:43
MOT test number	293687104293
Result	✓ Passed
Next expiry date	2024-06-05
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Rear Tyre worn close to legal limit/worn on edge nearside /offside worn on edge (5.2.3 (e))

**MOT #12**

2023-05-18 11:20

**MOT test number**

940645373029

**Result****✗ Failed****Fail**

Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

**Advice**

Covers/undertrays fitted preventing full inspection

**Advice**

Front Items removed from driver's view prior to test

**Fail**

Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice**

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Minor**

Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Fail**

Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

**Fail**

Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt retaining clip missing (2.1.3 (g) (ii))

**Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge wear on edge (5.2.3 (e))

**Minor**

Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #11**

2022-05-12 13:51

**MOT test number**

821487545626

**Result****✓ Passed****Advice**

Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #10**

2022-05-11 14:05

**MOT test number**

644096493647

**Result****✗ Failed**

- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Suspension arm pin or bush excessively worn rear wishbone bush loose and worn (5.3.4 (a) (i))
- Fail** Nearside Rear Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Offside Front Suspension arm pin or bush excessively worn rear wishbone bush (5.3.4 (a) (i))
- Fail** Offside Rear Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))

**MOT #9**

2021-08-06 12:21

**MOT test number**

192383714347

**Result****✓ Passed**

- Advice** Advise o/s n/s front brake discs corroded but not excessive
- Advice** Advise o/s n/s front lower suspension arm rear bushes worn but not excessive

**MOT #8**

2020-08-06 13:07

**MOT test number**

306719042352

**Result****✓ Passed****MOT #7**

2019-08-06 13:48

**MOT test number**

744240904468

**Result****✓ Passed**

**MOT #6** 2018-08-10 09:52**MOT test number** 779811159826**Result** ✓ Passed**MOT #5** 2017-07-26 13:13**MOT test number** 132958252740**Result** ✓ Passed

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**MOT #4** 2016-08-08 15:44**MOT test number** 112585672380**Result** ✓ Passed**MOT #3** 2015-12-14 17:03**MOT test number** 591506598943**Result** ✓ Passed**MOT #2** 2014-12-22 15:51**MOT test number** 666736354330**Result** ✓ Passed

**Notice** O/s/r tyre on 3mm

**Notice** N/s/r tyre on 2mm -205/50/r17

**MOT #1** 2013-12-23 15:14**MOT test number** 108457153369**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 May 2025

✓  
**MOT**  
  
Expires:  
5 June 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	5 June 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2019-01-01
Current registration	 <b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-03-23
Last registration	2023-06-06
Complete history	<a href="#">See info</a>



Registration #1	2011-03-23	21 mi
Registration #2	2013-12-23	19.673 mi
Registration #3	2014-12-22	25.424 mi
Registration #4	2015-12-14	29.328 mi
Registration #5	2016-08-08	31.504 mi
Registration #6	2017-07-26	53.097 mi
Registration #7	2018-08-10	73.721 mi
Registration #8	2019-08-06	93.153 mi
Registration #9	2020-06-20	111.277 mi
Registration #10	2021-06-20	129.377 mi
Registration #11	2022-06-20	147.477 mi
Registration #12	2023-06-20	165.577 mi
Registration #13	2024-06-20	183.677 mi
Registration #14	2025-06-20	201.777 mi
Registration #15	2026-06-20	219.877 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	1708102