



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | MAZDA |
| Model | MX-5 I |
| Colour | Silver |
| Year of manufacture | 2003 |
| Top speed | 128 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 144 BHP |
| Max. torque | 168 Nm at 5.000 rpm |
| Engine capacity | 1.840 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 24.8 mpg |
| Consumption extra urban | 39.8 mpg |
| Consumption combined | 32.5 mpg |
| CO2 emission | 210 g/km |
| CO2 label | K |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-05-24 |
| Pictures | 10 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2023-11-30 |
| MOT pass rate | 85 % |
| MOT passed | 17 |
| Failed MOT tests | 3 |
| Total advice items | 17 |
| Total items failed | 3 |

MOT #20 2024-03-26 16:00

MOT test number 133921428759

Result ✗ Failed

Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))

MAJOR Nearside Front Lower Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

MAJOR Offside Headlamp insecure (4.1.1 (c))

MAJOR Nearside Parking brake inoperative on one side (1.4.1 (a))

Advice Nearside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement
Both bushes perished (5.3.4 (a) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material Adjacent to flexible hose
(1.1.11 (c))

Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

MAJOR Front Brakes imbalanced across an axle (1.2.1 (b) (i))

MAJOR Offside Front Service brake excessively binding (1.2.1 (f))

Advice Offside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement
Both bushes perished (5.3.4 (a) (i))

MOT #19 2022-12-01 18:00

MOT test number 345619808576

Result ✓ Passed

**MOT #18** 2022-10-06 14:07**MOT test number** 352796708179**Result** ✗ Failed**DANGEROUS** Offside Rear Service brake has no recorded effort at a wheel (1.2.1 (a) (ii))**MAJOR** Offside Rear Parking brake inoperative on one side (1.4.1 (a))**MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #17** 2021-09-18 09:01**MOT test number** 248664283168**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))**MOT #16** 2020-09-05 12:56**MOT test number** 918392910266**Result** ✓ Passed**MOT #15** 2019-09-20 12:22**MOT test number** 663533859185**Result** ✓ Passed**MOT #14** 2017-12-27 11:31**MOT test number** 612154093476**Result** ✓ Passed**MOT #13** 2016-12-01 11:45**MOT test number** 582255630806**Result** ✓ Passed



| | |
|---|------------------|
| MOT #12 | 2015-10-28 11:47 |
| MOT test number | 977696463151 |
| Result | ✓ Passed |
| MOT #11 | 2014-11-27 09:26 |
| MOT test number | 577601234320 |
| Result | ✓ Passed |
| MOT #10 | 2013-09-05 10:50 |
| MOT test number | 319348343291 |
| Result | ✓ Passed |
| <div>Notice Os and ns front & rear tyres perished</div> | |
| MOT #9 | 2013-08-31 10:58 |
| MOT test number | 145183843274 |
| Result | ✗ Failed |
| <div>Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)</div> <div>Notice Os and ns front & rear tyres perished</div> | |
| MOT #8 | 2012-08-31 15:17 |
| MOT test number | 939534842290 |
| Result | ✓ Passed |
| MOT #7 | 2011-09-01 14:18 |
| MOT test number | 799804241206 |
| Result | ✓ Passed |
| MOT #6 | 2010-08-18 11:28 |
| MOT test number | 351660430266 |
| Result | ✓ Passed |



| | |
|------------------------|------------------|
| MOT #5 | 2009-10-15 10:41 |
| MOT test number | 560328689278 |
| Result | ✓ Passed |
| MOT #4 | 2008-10-18 10:14 |
| MOT test number | 103762798281 |
| Result | ✓ Passed |
| MOT #3 | 2008-06-16 15:51 |
| MOT test number | 572448268103 |
| Result | ✓ Passed |
| MOT #2 | 2007-06-05 14:11 |
| MOT test number | 961996957184 |
| Result | ✓ Passed |
| MOT #1 | 2006-06-07 09:46 |
| MOT test number | 342578856103 |
| Result | ✓ Passed |



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

| | |
|----------|--|
| Damage 1 | |
| Date | |
| Category | |
| Type | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this MAZDA had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-09-29 |
| Current registration | ***** |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 22 |
| First mileage registration | 2003-05-29 |
| Last registration | 2024-03-26 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2003-05-29 | 9 mi |
| Registration #2 | 2006-06-07 | 6.067 mi |
| Registration #3 | 2007-06-05 | 8.898 mi |
| Registration #4 | 2008-06-16 | 12.115 mi |
| Registration #5 | 2008-10-18 | 12.833 mi |
| Registration #6 | 2009-10-15 | 14.448 mi |
| Registration #7 | 2010-08-18 | 15.249 mi |
| Registration #8 | 2011-09-01 | 16.921 mi |
| Registration #9 | 2012-08-31 | 18.127 mi |
| Registration #10 | 2013-08-31 | 19.188 mi |
| Registration #11 | 2013-09-05 | 19.188 mi |
| Registration #12 | 2014-09-05 | 20.249 mi |
| Registration #13 | 2015-09-05 | 21.310 mi |
| Registration #14 | 2016-09-05 | 22.371 mi |
| Registration #15 | 2017-09-05 | 23.432 mi |
| Registration #16 | 2018-09-05 | 24.493 mi |
| Registration #17 | 2019-09-05 | 25.554 mi |
| Registration #18 | 2020-09-05 | 26.615 mi |
| Registration #19 | 2021-09-05 | 27.676 mi |
| Registration #20 | 2022-09-05 | 28.737 mi |
| Registration #21 | 2023-09-05 | 29.798 mi |
| Registration #22 | 2024-03-26 | 30.859 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1680 mm |
| Height | 1225 mm |
| Length | 3975 mm |
| Wheel base | 2265 mm |
| Kerb weight | 1065 kg |
| Max. allowed weight | 1305 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 50 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of axles | 2 |
| Engine number | BP 539229 |