



AD090JS

report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Grey
Year of manufacture	2009
Top speed	123 mph
0 - 60 mph	9.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	330 Nm at 1.800 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-05-26
Pictures	41
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-19
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	18
Total items failed	10

MOT #20	2023-12-18 15:38
MOT test number	534259578596
Result	✓ Passed
Next expiry date	2024-12-19

MOT #19	2023-12-18 09:45
MOT test number	906561527513
Result	✗ Failed
Fail	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #18	2022-12-13 10:55
MOT test number	472153767279
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Both on inner face (1.1.14 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2.6mm (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #17** 2021-12-20 11:14**MOT test number** 292803155207**Result** ✓ Passed**Advice** Top covers under trays sill covers fitted**MOT #16** 2021-12-16 15:29**MOT test number** 182833672453**Result** ✗ Failed**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Top covers under trays sill covers fitted**MOT #15** 2021-02-19 13:24**MOT test number** 751779749163**Result** ✓ Passed**MOT #14** 2021-02-05 13:27**MOT test number** 480311025691**Result** ✗ Failed**Fail** Offside Rear Lower Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))**Advice** Offside Vehicle structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #13** 2020-02-26 08:48**MOT test number** 242734895992**Result** ✓ Passed

**MOT #12** 2019-08-16 15:44**MOT test number** 271325187233**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2018-05-21 09:11**MOT test number** 235547549031**Result** ✓ Passed**MOT #10** 2018-05-21 09:11**MOT test number** 711239664883**Result** ✗ Failed

- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #9 2017-05-24 09:42**MOT test number** 602004060466**Result** ✓ Passed

- Advice** Offside front tyre valve perished
- Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #8** 2017-05-24 09:11**MOT test number** 544476304416**Result** ✗ Failed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Offside front tyre valve perished**Fail** Offside Headlamp aim too low (1.8)**MOT #7** 2016-05-27 09:24**MOT test number** 429705749894**Result** ✓ Passed**MOT #6** 2016-05-23 09:05**MOT test number** 977317262149**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**MOT #5** 2015-05-28 09:59**MOT test number** 249688645150**Result** ✓ Passed**MOT #4** 2014-05-27 11:12**MOT test number** 218667444190**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2013-05-08 15:40
MOT test number	527628423179
Result	✓ Passed
MOT #2	2012-05-11 11:21
MOT test number	307942032129
Result	✓ Passed
MOT #1	2012-05-11 11:21
MOT test number	129582232105
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
19 December 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	19 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,200
Auction value	£ 19,200
Average private trade value	£ 19,200

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-05-27
Last registration	2023-12-18
Complete history	See info



Registration #1	2009-05-27	20 mi
Registration #2	2012-05-11	31.993 mi
Registration #3	2013-05-08	41.753 mi
Registration #4	2014-05-27	43.274 mi
Registration #5	2015-05-28	44.326 mi
Registration #6	2016-05-23	45.040 mi
Registration #7	2016-05-27	45.056 mi
Registration #8	2017-05-24	45.838 mi
Registration #9	2017-05-24	45.838 mi
Registration #10	2018-05-21	46.115 mi
Registration #11	2018-05-21	46.115 mi
Registration #12	2019-05-20	46.115 mi
Registration #13	2019-05-20	46.115 mi
Registration #14	2019-05-20	46.115 mi
Registration #15	2019-05-20	46.115 mi
Registration #16	2019-05-20	46.115 mi
Registration #17	2019-05-20	46.115 mi
Registration #18	2019-05-20	46.115 mi
Registration #19	2019-05-20	46.115 mi
Registration #20	2019-05-20	46.115 mi
Registration #21	2019-05-20	46.115 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Max. allowed weight	2075 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	0811191141116G